

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref

305482820

Via Fax

BMAL

Date

16.0821

Your Insured

SKP8382 E

Time of Fax

Date of Acc

13.08.21

Attn: Motor Claims Department

ALG

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH C 81624

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Lim Kwok Eng

Tel: 6214 8355 or HP: 9824 0811

◆ Jumani Bin Masudin◆ Lim Tien Siong

Tel: 6214 8315 or HP: 9635 5305 Tel: 6214 8398 or HP: 9635 8546

Fax no. 6546 8156

chianglc@cdge.com.sg

♦ Chiang Liat Choon

Tel: 6214 8314 or HP: 9296 6006

If we do not hear from you within the <u>next 48 hours</u>, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Taxi Accident Repair

COMFORTDELGRO ENGINERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8152G

DATE 13.08.2021

MAKE

:

CHIANG/AIG

MODEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$1,052.20
1	HEAD LAMP LH			\$1,388.00
10	BUMPER CLIP			\$22.00
1	FRONT BUMPER GRILLE LH			\$93.60
1	FRONT BUMPER BRACKET TOP LH			\$22.80
1	FRONT WHEEL COVER LH			\$217.20
1	FRONT FENDER LH			\$663.00
	SUB TOTAL			\$3,458.80
	20.00%			\$69.76
				\$2,767.04
1	FRONT FENDER ADVERTISEMENT			\$100.00
				\$100.00
			ì	
	Labour Charge			
	Panel Beating			\$560.00
	Spray paintimg			\$600.00
	Reset front wheel alignment			\$60.00
	Check Lighting			\$60.00
	TOTAL LABOUR			\$1,280.00
	ESTIMATE TOTAL			\$4,147.04
				. ,
	This is an initial estimate based on a visual inspection of the	above ve	icle. The final repair q	antum will
	pe prepared after the vehicle is surveyed by a motor Survey	or appoint	ed by the insurance co	mpany.