

IMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8152G

DATE 13.08.2021

MAKE :

CHIANG/AIG

MODEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER		del	\$1,052.20
1	HEAD LAMP LH		nn x	\$1,388.00
10	BUMPER CLIP		all	\$22.00
1	FRONT BUMPER GRILLE LH		x	\$93.60
1	FRONT BUMPER BRACKET TOP LH		x	\$22.80
1	FRONT WHEEL COVER LH		x	\$217.20
1	FRONT FENDER LH		x	\$663.00
	SUB TOTAL		1074.20	\$3,458.80
	20.00%		859.36	\$69.76
				\$2,767.04
1	FRONT FENDER ADVERTISEMENT		net	\$100.00
			100	\$100.00
	Labour Charge			
	Panel Beating		280	\$560.00
	Spray painting		250	\$600.00
	Reset front wheel alignment		30	\$60.00
	Check Lighting		nn	\$60.00
	TOTAL LABOUR		1489.36	\$1,280.00
	ESTIMATE TOTAL		151200	\$4,147.04
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tanpin 974 9744
 'wp' 16/8/21 24157
 1/2 heavy after repair
 2 days
 Tanpin @ 16/8/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Cor., any

Acknowledged by Repairer
 Signature:
 Date: