

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21008568/AGA3Q2
Date: 05/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100273832
Claimant Vehicle No :	SLZ7202J	Insured Vehicle No :	SKC7305D
Date of Loss:	15/08/2021	Nature of Claim:	TP
		Claim No:	7658124307SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ7202J	Engine No:	DAX033085
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Chassis No:	WAUZZZFY3J2138343
Reg. Date:	16/05/2018 (Man. Year: 2018)	Odometer:	60337 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,170.00	4,108.00	5,062.00	55.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,752.00	2,552.00	2,200.00	46.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,922.00	6,660.00	7,262.00	52.16
+ GST 7.00/7.00% (S\$)	974.54	466.20	508.34	52.16

Nett Amount (\$\$)	14,896.54	7,126.20	7,770.34	52.16
+ Loss of Use (3.0 x S\$100.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		7,428.20		

INSPECTION

Date of Assignment: 20/08/2021

Date Inspected: 20/08/2021

Estimated Period of Repair: 3.0 days

Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER -UPPER	Deformed	1,907.00 FS	*1,525.60 FS
2	1		*REAR BUMPER -LOWER	Deformed	1,196.00 FS	*956.80 FS
3	1		*REAR BUMPER SPOILER	Deformed	866.00 FS	*692.80 FS
4	2		*REAR BUMPER TOWING EYE COVER -LH/RH	Not Necessary	77.00 FS	*- FS
5	2		*REAR BUMPER CLOSING ELEMENT -LH/RH	Not Necessary	192.00 FS	*- FS
6	2		*REAR BUMPER TRIM LH/RH	Not Necessary	474.00 FS	*- FS
7	2		*REAR TAIL LIGHT -LH/RH	Not Necessary	1,398.00 FS	*- FS
8	1		*REAR BOOT LID CONTROL UNIT	Not Necessary	411.00 FS	*- FS
9	1		*REAR BUMPER REINFORCEMENT	Not Necessary	981.00 FS	*- FS
10	8		*HEXAGON	Not Necessary	64.00 FS	*- FS
11	2		*REAR BUMPER SEAL	Not Necessary	6.00 FS	*- FS
12	1		*REAR BUMPER HOLDING STRAP	Not Necessary	168.00 FS	*- FS
13	2		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
14	4		*REAR PARKING AID SENSOR SEAL	Not Necessary	14.00 FS	*- FS
15	2		*REAR WHEEL ARCH COVER -LH/RH	Necessary	1,166.00 FS	*932.80 FS
16	1		*SUDRIES	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)
9,170.00
4,108.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER ,REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	New	3,000.00	1,500.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,752.00	2,552.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >