

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0657/2021/ZK
DATE : 16-Aug-21
WIP : 39808

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 20/8/2021
YOUR INSURED VEH NO : SKC 7305 D

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LAU CHOON MUN
ADDRESS : BLK 637 WOODLANDS RING ROAD
#09-61
SINGAPORE 730637
TELEPHONE : HP +65 97898184
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800053161-03
VEHICLE NO : **SLZ 7202 J**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI
MODEL YEAR : 16/5/2018
ENGINE NO : DAX 033085
CHASSIS NO : WAUZZZF3J2138343
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Aug-21
PLACE OF ACCIDENT : ALONG CTE BEFORE ANG MO KIO AVE 1 EXIT ON LANE 1

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLZ 7202 1

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	S/N \$	360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00 500.	
3	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	\$	3,000.00 1500.	Bumper 550 Lower Bumper 350
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓ Arch Trim : 200 x 2 = 400.
TOTAL LABOUR CHARGES		: \$	<u><u>4,752.00</u></u>	<u>1300</u>

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 7202 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER - UPPER ?	1	\$ 1,907.00	✓
2	REAR BUMPER - LOWER {behind	1	\$ 1,196.00	✓
2	REAR BUMPER SPOILER	1	\$ 866.00	✓
3	REAR BUMPER TOWING EYE COVER - LH / RH {new	2	\$ 77.00	+
4	REAR BUMPER CLOSING ELEMENT - LH / RH	2	\$ 192.00	x
5	REAR BUMPER TRIM - LH / RH ?	2	\$ 474.00	+
6	REAR TAIL LIGHT - LH / RH {new	2	\$ 1,398.00	+
7	REAR BOOT LID CONTROL UNIT	1	\$ 411.00	+
8	REAR BUMPER REINFORCEMENT	1	\$ 981.00	+
9	HEXAGON {new	8	\$ 64.00	+
10	RAER BUMPER SEAL	2	\$ 6.00	+
11	REAR BUMPER HOLDING STRAP ?	1	\$ 168.00	?
12	REAR PARKING AID SENSOR {new	2	TBC	+
13	REAR PARKING AID SENSOR SEAL	4	\$ 14.00	x
14	REAR WHEEL ARCH COVER - LH / RH new	2	\$ 1,166.00	✓
15	SUDRIES ?		\$ 250.00	?
TOTAL SPARE PARTS		:	\$ 9,170.00	
TOTAL LABOUR CHARGES		:	\$ 4,752.00	
GRAND TOTAL		:	\$ 13,922.00	

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *20/08/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT