



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0657/2021/ZK
DATE : 16-Aug-21
WIP : 39808

Celia

~~\$6600~~

\$6660.00

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 20/8/2021

YOUR INSURED VEH NO : SKC 7305 D

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LAU CHOON MUN
ADDRESS : BLK 637 WOODLANDS RING ROAD
#09-61
SINGAPORE 730637
TELEPHONE : HP +65 97898184
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800053161-03
VEHICLE NO : SLZ 7202 J
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI
MODEL YEAR : 16/5/2018
ENGINE NO : DAX 033085
CHASSIS NO : WAUZZZF3J2138343
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Aug-21
PLACE OF ACCIDENT : ALONG CTE BEFORE ANG MO KIO AVE 1 EXIT ON LANE 1

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLZ 72021

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	S/N \$ 360.00 ✓	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00 ✓	500.
3	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	\$ 3,000.00 ✓	1500. Bumper 550 Lower Bumper 350 Arch Trim 200x2 = 400.
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 4,752.00	1350

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 7202 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER - UPPER	1	\$ 1,907.00	✓ \$1,525.60
2	REAR BUMPER - LOWER	1	\$ 1,196.00	✓ \$956.80
2	REAR BUMPER SPOILER	1	\$ 866.00	✓ \$692.80
3	REAR BUMPER TOWING EYE COVER - LH / RH	2	\$ 77.00	✗
4	REAR BUMPER CLOSING ELEMENT - LH / RH	2	\$ 192.00	✗
5	REAR BUMPER TRIM - LH / RH	2	\$ 474.00	✗
6	REAR TAIL LIGHT - LH / RH	2	\$ 1,398.00	✗
7	REAR BOOT LID CONTROL UNIT	1	\$ 411.00	✗
8	REAR BUMPER REINFORCEMENT	1	\$ 981.00	✗
9	HEXAGON	8	\$ 64.00	✗
10	REAR BUMPER SEAL	2	\$ 6.00	✗
11	REAR BUMPER HOLDING STRAP	1	\$ 168.00	✗
12	REAR PARKING AID SENSOR	2	TBC	✗
13	REAR PARKING AID SENSOR SEAL	4	\$ 14.00	✗
14	REAR WHEEL ARCH COVER - LH / RH	2	\$ 1,166.00	✓ \$932.80
15	SUNDRIES		\$ 250.00	✗
TOTAL SPARE PARTS		:	\$ 9,170.00	
TOTAL LABOUR CHARGES		:	\$ 4,752.00	
GRAND TOTAL		:	\$ 13,922.00	

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

★ PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian L
: 20/08/21

:
: we Authorised, 03 Days. H.S.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT