

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008569/EBS3Q2
Date: 07/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993682
Claimant Vehicle No :	GBG8160H	Insured Vehicle No :	GBK4160M
Date of Loss:	28/06/2021	Nature of Claim:	TP
		Claim No:	5230417240SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG8160H	Engine No:	YD25000640B
Make & Model:	NISSAN NV350, 2.5 (A)	Chassis No:	JN1MC2E26Z0009516
Reg. Date:	02/11/2017 (Man. Year: 2017)	Odometer:	186392 km
Colour:	Grey		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,366.00	2,907.70	1,458.30	33.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	1,030.00	980.00	48.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,376.00	3,937.70	2,438.30	38.24
Approved Total (Overridden) (S\$)		3,150.00		

(S\$)	6,376.00	3,150.00	3,226.00	50.60
+ GST 7.00/7.00% (S\$)	446.32	220.50	225.82	50.60
Nett Amount (S\$)	6,822.32	3,370.50	3,451.82	50.60
+ Car Rental (4.0 x S\$125.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,912.95		
Global Sum Settlement (S\$)		3,800.00		

INSPECTION

Date of Assignment: 16/08/2021

Date Inspected: 16/08/2021 Inspected At: Million Auto Service (HQ)
 No. 2 Penjuru Place #01-12 2.8 Penjuru Tech Hub, Blk 882 Jurong West #02-394 Street 81
 Singapore 608782

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE ASSY	Dented	1,816.70 F	*1,816.70 F
2	1		*TAIL GATE OUTER GARNISH	Not Necessary	535.70 F	*- F
3	1		*TAIL GATE EMBLEM	Necessary	79.90 F	*79.90 F
4	1		*TAIL GATE LOCK	Jammed	287.10 F	*287.10 F
5	1		*TAIL GATE LOCK COVER	Not Necessary	54.20 F	*- F
6	1		*TAIL GATE RUBBER	Not Necessary	154.30 F	*- F
7	1		*TAIL GATE AUTOLOCK ACTUATOR	Not Necessary	255.90 F	*- F
8	1		*REAR BUMPER	Dented	600.50 F	*600.50 F
9	1		*REAR BUMPER RETAINER	Broken	18.50 F	*18.50 F
10	1		*REAR BUMPER STEP PANEL	Not Necessary	164.20 F	*- F
11	1		*REAR END PANEL OUTER	Not Necessary	246.50 F	*- F
12	5		*REAR BUMPER CLIPS	Necessary	42.50 F	*25.00 F
13	1		*70KM/H STICKER	Necessary	25.00 F	*20.00 F
14	1		*7 PAX STICKER	Necessary	25.00 F	*20.00 F
15	1		*WINDSCREEN SEALANT	Necessary	60.00 F	*40.00 F
F=Franchise part.						
					Total Parts (\$\$)	4,366.00
						2,907.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & ASSEMBLY REAR WINDSCREEN	New	190.00	120.00
2	TO SPRAY PAINT & PUTTY AFFECTED AREA	New	780.00	400.00
3	TO APPLY AUTI RUST PROOFING ON AFFECTED AREA	New	120.00	0.00
4	TO REMOVE & REFIX REVERSE CAMERA & CHECK WIRING	New	190.00	60.00
5	TO REMOVE & TRANSFER TAILGATE MECHANISM	New	50.00	50.00
6	LABOUR CHARGE FOR PANEL BEATING REAR PANEL & AFFECTED PARTS	New	680.00	400.00
Gross Labour Cost (S\$)			2,010.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >