

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |   |   |                 |                      |  |
|---|---|---|-----------------|----------------------|--|
|   | AXA INSURANCE   | PTE LTD   | Ref:            | CS/ASM21008572/Etce2 |  |
|   | 8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811   |   | Date:           | 25/08/2021           |  |
|   | ATTN: TEO KITTY   |   | Code:           | ASM                  |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM   |   |                 |                      |  |
|   | Insured Veh.  | SMR 9589K   | Veh. Inspected  | SMX 5002G            |  |
|   | Policy No.  | P2381217  | Coverage (\$)   | 0.00                 |  |
|   | Claim No.   | S1M03FJ1  | Excess (\$)     | 0.00                 |  |
|   | Assign From   | TEO KITTY   | Assign Date     | 16/08/2021           |  |
| 2. Vehicle Particulars & Condition                                |   |   |                 |                      |  |
|   | Make & Model  | SUBARU IMPREZA  | c.c             | 1600                 |  |
|   | Engine No.  | HIDDEN  | Year of Reg.    | 2017                 |  |
|   | Chassis No.   | JF1GT3KC5HG006011   | Colour          | WHITE                |  |
|   | Odometer  | 70220 KM  | Steering        | IN ORDER             |  |
|   | Brakes  | IN ORDER  | Modification    | SPORTS RIM           |  |
|   | General   | GOOD  |                 |                      |  |
| 3. Conditions of Tyres  |   |   |                 |                      |  |
|   |   | Size  | Make            | Balance              |  |
|   | R/H Front Tyre  | 205/50 R17  | CONTINENTAL     | 5 mm                 |  |
|   | L/H Front Tyre  | 205/50 R17  | CONTINENTAL     | 5 mm                 |  |
|   | R/H Rear Tyre   | 205/50 R17  | CONTINENTAL     | 5 mm                 |  |
|   | L/H Rear Tyre   | 205/50 R17  | CONTINENTAL     | 5 mm                 |  |
| 4.  | Description of Damages  |   |                 |                      |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  |   |                 |                      |  |
|   | DAMAGES SEE DETAILS.  |   |                 |                      |  |
| 5.  | General Information   |   |                 |                      |  |
|   | Accident Date   | 08/08/2021  | Inspection Date | 17/08/2021           |  |
|   | Survey held at  | neld at BLK 6 WOODLANDS ROAD 399J YEW TEE IND EAT S678008 |                 |                      |  |
|   | Repairer  | CAR PRO AUTO  |                 |                      |  |
| 5a.   | Remarks   |   |                 |                      |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |                      |  |
| 5b.   | Estimate Days of Repair   |   |                 |                      |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days  |   |                 |                      |  |
|   | <u> </u>  |   |                 |                      |  |