

Adjustment of Spare Parts Costs for Repairs SMX5002G Subaru Impreza

Item	Qty	Vehicle Parts Description		
1	1pc	Rear Bumper / DD	\$ 800.00	648-
2	1pc	Rear Bumper Lower Skirt Garnish / CVT	\$ 650.00	450-
3	2pc	Rear Bumper Reflector Lamp LH/RH x nn	\$ 320.00	
4	2pc	Rear Bumper Side Retainer LH/RH - BR	\$ 180.00	140-
5	1pc	Rear Bumper Reinforcement - DD	\$ 550.00	382-
6	1Set	Rear Bumper Clips - nec	\$ 38.00	30-
7	1pc	Rear Tailgate x R	\$ 1,150.00	
8	1pc	Rear Tailgate Subaru Emblem - nec	\$ 150.00	90-
9	1pc	Rear Tailgate Impreza Emblem - nec	\$ 85.00	-
10	1pc	Rear Tailgate Centre Garnish - CVT	\$ 310.00	270-
11	1Set	Rear Tailgate Centre Garnish Fasteners - nec	\$ 38.00	10-
12	1pc	Rear Tailgate W/screen Moulding x nn	\$ 285.00	
13	2pcs	Rear Tailgate Lamp LH/RH (LH) - CVT	\$ 760.00	380-
14	1pc	Rear Tailgate Inner Lock x nn	\$ 298.00	
15	1pc	Rear Tailgate Inner Weatherstrip x nn	\$ 285.00	
16	1pc	Rear Tailgate Inner Trim Board x nn	\$ 330.00	
17	1Set	Rear Tailgate Inner Trim Board Clips x nn	\$ 38.00	
18	2pcs	Rear Taillamp LH/RH x nn	\$ 860.00	
19	1pc	Rear End Panel x nn	\$ 650.00	
20	1pc	Rear End Panel Top Garnish x nn	\$ 320.00	
21	2pcs	Rear Fender Inner Trim Board LH/RH x nn	\$ 1,280.00	
22	2Set	Rear Fender Inner Trim Board Clips x nn	\$ 75.00	
23	1pc	Rear Spare Tyre Panel x nn	\$ 880.00	
24	1pc	Rear Spare Tyre Top Cover x nn	\$ 450.00	
			\$ 10,782.00	3275
Less 20%			\$ 2,156.40	-20%
			\$ 8,625.60	1620

Special Nett Item

1	Reverse Sensor	\$ 200.00	-
1	Reverse Camera	\$ 250.00	x nn
1	Rear Windscreen Sealant	\$ 80.00	x nn
1	Rear End Panel Sealant	\$ 80.00	x nn
1	Rear Spare Tyre Panel Sealant	\$ 80.00	x nn
1	Subaru Original In-Build LCD Screen	\$ 3,200.00	x nc
			\$ 3,890.00

200

Adjustment of Labour Costs for Repairs

Spraying of affected area	\$	600.00	400
Carry out body cavity preservation	\$	100.00	30
To remove and replace damage parts including straightening & repositioning replacement parts & panel beat	\$	800.00	300
Remove & refix rear windscreen	\$	150.00	X
Check wiring	\$	60.00	30
Remove/refix boot compartment fitting and attachments for	\$	80.00	X
Remove & refix reverse camera	\$	80.00	X
Remove & refix reverse sensor	\$	80.00	30
Remove & refix tailgate components	\$	80.00	X
Remove & refix front in-build LCD screen	\$	150.00	X
	\$	2,180.00	

Steve (LKK)

17/8/21

w/p

Resuney After Spray

L/S

3 days

$$\begin{array}{r}
 790 \\
 = 4400 \\
 L/S - 3520 \\
 = 3500
 \end{array}$$

14695.60

