

## Adjustment of Spare Parts Costs for Repairs SMX5002G Subaru Impreza

Item	Qty	Vehicle Parts Description		
1	1pc	Rear Bumper / DD	\$	800.00 /
2	1pc	Rear Bumper Lower Skirt Garnish / CVT	\$	650.00 450-
3	2pc	Rear Bumper Reflector Lamp LH/RH x nn	\$	320.00
4	2pc	Rear Bumper Side Retainer LH/RH / BR	\$	180.00 140-
5	1pc	Rear Bumper Reinforcement / DD	\$	550.00 382-
6	1Set	Rear Bumper Clips / nec	\$	38.00 30-
7	1pc	Rear Tailgate x R	\$	1,150.00
8	1pc	Rear Tailgate Subaru Emblem / nec	\$	150.00 /
9	1pc	Rear Tailgate Impreza Emblem / nec	\$	85.00 /
10	1pc	Rear Tailgate Centre Garnish / CVT	\$	310.00 270-
11	1Set	Rear Tailgate Centre Garnish Fasteners / nec	\$	38.00 10-
12	1pc	Rear Tailgate W/screen Moulding x nn	\$	285.00
13	2pcs	Rear Tailgate Lamp LH/RH (LH) / CVT	\$	760.00 380-
14	1pc	Rear Tailgate Inner Lock x nn	\$	298.00
15	1pc	Rear Tailgate Inner Weatherstrip x nn	\$	285.00
16	1pc	Rear Tailgate Inner Trim Board x nn	\$	330.00
17	1Set	Rear Tailgate Inner Trim Board Clips x nn	\$	38.00
18	2pcs	Rear Taillamp LH/RH x nn	\$	860.00
19	1pc	Rear End Panel x nn	\$	650.00
20	1pc	Rear End Panel Top Garnish x nn	\$	320.00
21	2pcs	Rear Fender Inner Trim Board LH/RH x nn	\$	1,280.00
22	2Set	Rear Fender Inner Trim Board Clips x nn	\$	75.00
23	1pc	Rear Spare Tyre Panel x nn	\$	880.00
24	1pc	Rear Spare Tyre Top Cover x nn	\$	450.00
			\$	10,782.00
Less 20%			\$	2,156.40
			\$	8,625.60

2697  
-20%  
2157.60

### Special Nett Item

1	Reverse Sensor	\$	200.00 /
1	Reverse Camera	\$	250.00 x nn
1	Rear Windscreen Sealant	\$	80.00 x nn
1	Rear End Panel Sealant	\$	80.00 x nn
1	Rear Spare Tyre Panel Sealant	\$	80.00 x nn
1	Subaru Original In-Build LCD Screen	\$	3,200.00 x nc
		\$	3,890.00

## Adjustment of Labour Costs for Repairs

Spraying of affected area	\$	600.00	400
Carry out body cavity preservation	\$	100.00	30
To remove and replace damage parts including straightening & repositioning replacement parts & panel beat	\$	800.00	300
Remove & refix rear windscreen	\$	150.00	X
Check wiring	\$	60.00	30
Remove/refix boot compartment fitting and attachments for	\$	80.00	X
Remove & refix reverse camera	\$	80.00	X
Remove & refix reverse sensor	\$	80.00	30
Remove & refix tailgate components	\$	80.00	X
Remove & refix front in-build LCD screen	\$	150.00	X
		790	
	\$	2,180.00	

Steve (LKK)

17/8/21

w/p

Resurvey After Spray

L/S

3 days

