

ASS. REG. BY:

REF: 012 / 210085761K

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OO / TP / WS / LP / RES / OO / RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s Cheng Hoe
of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SL6 7768S Yr Regn: 03, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda VE31 c.o. 1496

Colour: M. Blue AC: Insured / Std / NI / NA

Sp. Reading: 110252 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KU1 1204943

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Double Star

Front Rear

R/Bal. 7 mm R/Bal. 9 mm

L/Bal. 7 mm L/Bal. 9 mm

D.O.A. 14/8/21 D.O.I. 16/8/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to? : Prell. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Report Format:

Lump Sum / I.B.I: (\$ _____)

SLL77683
TP/CHINA

REPAIR DETAILS

Reference

Part Source: MRM SG Version: 1.0 (Last Synchronised: 16 Aug 2021)
 Parts: MFSUV MONDA VEZEL 1.3 (A) (Catalogue Merimen Singapore 1.0)
 Labour: Repairer's (Price Determined Standard List)
 Print Code: (Unsubmitted, no print code for SLL77683)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT BUMPER	0.00	0.00	*190.00F
2	1		*1 PC FRT BUMPER REINFORCEMENT	0.00	0.00	*205.00F
3	1		*1 PC FRT BUMPER RH SIDE RETAINER	0.00	0.00	*10.00F
4	1		*1 PC FRT BUMPER LOWER SKIRT	0.00	0.00	*145.00F
5	1		*1 PC FRT BUMPER CENTRE LOWER GRILLE	0.00	0.00	*60.00F
6	1		*1 PC FRT BUMPER RH FOG LAMP	0.00	0.00	*135.00F
7	1		*1 PC FRT BUMPER RH FOG LAMP GARNISH	0.00	0.00	*18.00F
8	1		*8 PCS FRT BUMPER CLIPS @2/PC	0.00	0.00	*12.00F
9	1		*1 PC FRT GRILLE HOUSING	0.00	0.00	*200.00F
10	1		*1 PC FRT GRILLE TOP COVER	0.00	0.00	*160.00F
11	1		*4 PCS FRT GRILLE CLIPS @2/PC	0.00	0.00	*8.00F
12	1		*1 PC RH HEADLAMP	0.00	0.00	*880.00F
13	1		*1 PC RH HEADLAMP LOWER RETAINER	0.00	0.00	*25.00F
14	1		*1 PC RH HEADLAMP SIDE BRACKET	0.00	0.00	*15.00F
15	1		*1 PC LH HEADLAMP	0.00	0.00	*880.00F
16	1		*1 PC FRT RH FENDER	0.00	0.00	*190.00F
17	1		*1 PC FRT RH FENDER WHEEL ARP GARNISH	0.00	0.00	*60.00F
18	1		*1 PC FRT RH FENDER INNER PANEL	0.00	0.00	*180.00F
19	1		*1 PC FRT SUPPORT PANEL	0.00	0.00	*320.00F
20	1		*1 PC BONNET	0.00	0.00	*495.00F
21	1		*1 PC BONNET RH INNER RUBBER	0.00	0.00	*20.00F
22	1		*1 PC BONNET RH HINGE	0.00	0.00	*35.00F
23	1		*1 PC FRT WIPER TANK	0.00	0.00	*55.00F
Total Parts (\$\$)						4,298.00

Handwritten checkmarks and scribbles on the right side of the parts table.

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items


There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	REMOVE & REFIX FRT BUMPER ASSY,GRILLE,FOG LAMPS & GARNISHS,HEADLAMPS,BONNET & ATTACHMENT,CUT,WELD & RENEW FRT SUPPORT PANEL,FRT RH FENDER INNER PANEL & REALIGN THE SAME	New	980.00
2	REMOVE & REFIX AIR-CON,CHECK,VACUUM & REFILL GAS	New	100.00
3	PUTTY & RESPRAY ON FRT SUPPORT PANEL,BONNET,HINGES,FRT BUMPER,REINFORCEMENT,FR TFENDER & ALL AFFECTED AREAS	New	800.00
4	RUSTPROOFING	New	60.00
Gross Labour Cost (\$\$)			1,940.00

Handwritten checkmarks and scribbles on the right side of the labour table.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel: 67556142 Fax: 67557719

Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP CHINA
Policy No:		Date of Loss:	14/08/2021
Vehicle Reg. No.:	SLL7768S	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	MURUGESAN VIVEKANANDAN	Driver (Insured):	ONG WEI MENG
Make/Model:	HONDA VEZEL, 1.5 (A)	Vehicle Reg. Date:	09/03/2017
Vehicle Colour:	BLUE		
Engine No:	L15B4404948	Chassis No:	RU11204943
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	PLS REFER EFILE REPORT		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

*NOT Authorized
Recovery After Paint
1/1 Pmp @
5 days*

COST OF CLAIMS

	Amount
Parts	4,298.00
Miscellaneous Items	0.00
Labour	1,940.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,238.00
+ GST 7.00% (S\$)	436.66
Nett Amount (S\$)	6,674.66

This claim is handled by: JUNE PHUA LIAN HUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

<https://singapore.merimen.com/claims/index.cfm?fusebox=MTRrepairer&fuseaction=...> 16/08/2021

Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident occurred on 14/8/21 @ 1pm at No. 43
 Sungai Kadut Loop.
 My vehicle was parked besides the building and it
 was hit by m/truck XD6389J which was
 reversing.
 Damage to my vehicle - Front Right

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
 Date & Time:

m. [Signature]

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature] 14/8/21

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.: YS

- () Claim Own Policy () Claim Third Party () Reporting Only
 () Claim OD/TP at other workshop (_____)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 16/08/2021 13:04 (SGT)
Date of Accident 14/08/2021 13:00 (SGT)
Exact Location of Accident Singapore
Additional Location Information NO. 43 SUNGEI KADUT LOOP
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLL7768S

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner ARSU CONTRACTOR SERVICES PTE LTD
Company Reg No 2XXXXX963W
Email Address arsu@live.com.sg
Mobile Phone No (Phone) +65-91866967
Alternative Phone No (Office) +65-91866967

VEHICLE PARTICULARS

Manufacturer Honda
Model Vezel
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1500

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5119606160
Cover Note Number EXP 25.10.2021

DRIVER

Name of Driver MURUGESAN VIVEKANANDAN
Passport No/FIN GXXXX427R