

ESTIMATE OF REPAIR

Veh# : SCE1277A

TP III

Model:

MAZDA 3

Accident Date : 14/8/2021

Jasper.

(13/5/2015)

Location : CROSS JUNCTION BETWEEN MARINA BOULEVARD AND SHEARES AVE

3P:

SMM9479X (III)

JM6BM42A8G0308227

S/No s.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Rehd</i>	971.40	✓	
2	10 pcs	Front bumper clips <i>an</i>		20.00	✓
3	1 pc	Front bumper n/s fog lamp <i>Antid</i>	265.20	✓	
4	1 pc	Front bumper n/s fog lamp (Garnish) <i>ct</i>	86.50	✓	
5	1 pc	Front bumper n/s retainer <i>Ne</i>	64.00	✓	
6	2pcs	Front n/s & n/s grill cover (lower) <i>Ne</i>	80.00	+	
7	1 pc	Front n/s head lamp <i>ct</i>	1277.80	✓	
8	1 pc	Front n/s fender <i>Dented</i>	385.70	✓	
9	1 pc	Front n/s rim <i>ct</i>	1256.80	600 (SN)	
10	1 pc	Front n/s lower arm <i>Bent</i>	554.30	484	
11	1 pc	Front n/s tie rod end <i>3rd Ne</i>	249.40	+	
12	1 pc	Front n/s stabilizer linkage <i>3rd Ne</i>	168.00	+	
13	1 pc	Front n/s suspension <i>Bent</i>	460.80	381	
14	1 pc	Front n/s bearing <i>Bent</i>	658.80	361	
15	1 pc	Front n/s kunckle <i>Ne</i>	502.60	+	
16	1 pc	Front n/s tyre <i>Ne cut</i>		150.00	120
Sub-Total:			6,981.30	170.00	0.00
			20%	0%	0%
After Less %:			5,585.04	170.00	0.00

4252.60
3426.08
S/N: 740

	Labour	
1	To dismantle, straighten & welding.	800.00 <i>500</i>
2	To spray painting.	600.00 <i>400</i>
3	To check wheel alignment	150.00 <i>80</i>
4	To remove and replace front n/s under carriage	900.00 <i>200</i>
5	To check wiring.	50.00 <i>30</i>
6	To re-seal anti-rust.	30.00 <i>X</i>
Sub-Total:		1,930.00
Total:		7,685.04
AFTER LESS 20%		6,148.03

Adrian Ly
1/s 16/08/21.

05 Days

Supplementary: 168

Whole: 5544.08

4/s: A.H.K.

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

LKK Auto Consultants hence notify the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: *biSAFE*
Date:

AL 8778 1999
24 hr accident call

Mobil 1



2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : SCE1277A

Model: MAZDA 3

Accident Date : 14/8/2021

(13/5/2015)

Location : CROSS JUNCTION BETWEEN MARINA BOULEVARD AND SHEARES AVE

3P: SMM9479X (III)

<u>S/No</u> <u>S.</u>	<u>Qty</u>	<u>Description</u>	<u>List \$</u>	<u>S/Nett \$</u>	<u>Nett \$</u>
1	1 pc	Front n/s fender inner trim <i>Rehd</i>	210.00	☒	
		Sub-Total:	210.00	0.00	0.00
			20%	0%	0%
		After Less %:	168.00	0.00	0.00

210.
Supplementary: 168

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



8778 1999
24 hr accident call

Mobil 1

