



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN		Ref: CC4/ASM21008584/Urs3q2 Date: 01/12/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMS 3663M	Veh. Inspected	SBM 1110S
Policy No.	GA560895	Coverage (\$)	0.00
Claim No.	S1M03FOV	Excess (\$)	0.00
Assign From		Assign Date	16/08/2021
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ GLA180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	WDC1569422J685539	Colour	BLACK
Odometer	19240 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50 R18	CONTINENTAL	7 mm
L/H Front Tyre	235/50 R18	CONTINENTAL	7 mm
R/H Rear Tyre	235/50 R18	CONTINENTAL	7 mm
L/H Rear Tyre	235/50 R18	CONTINENTAL	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/08/2021	Inspection Date	16/08/2021
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	