

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21008585/APA3Q2
Date: 20/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372
Claimant Vehicle No :	SKW9459A	Insured Vehicle No :	SHD2147G
Date of Loss:	11/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003482

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW9459A		
Make & Model:	TOYOTA ALPHARD, 2.5 CVT ELEGANCE S/R (A)	Engine No:	2ARH650558
Reg. Date:	23/11/2015 (Man. Year: 2015)	Chassis No:	JTNGF3DH408003124
Colour:	White	Odometer:	111052 km
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,215.60	1,339.12	2,876.48	68.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	1,010.00	730.00	41.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,955.60	2,349.12	3,606.48	60.56
Approved Total (Overridden) (S\$)		1,850.00		

(S\$)	5,955.60	1,850.00	4,105.60	68.94
+ GST 7.00/7.00% (S\$)	416.89	129.50	287.39	68.94
Nett Amount (S\$)	6,372.49	1,979.50	4,392.99	68.94
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,286.95		

INSPECTION

Date of Assignment: 16/08/2021

Date Inspected: 18/08/2021

Estimated Period of Repair: 3.0 days

Inspected At: KAI MOTOR TRADING (HQ)
BLK 3007 UBI ROAD 1, #01-440
Singapore 408701

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2021)
Parts:	M1-MPV	TOYOTA ALPHARD 2.5 CVT ELEGANCE S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW9459A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CENTRE DOOR	Repair	2,500.20 FL	*- FL
2	1		*FRONT DOOR RH	Dented	1,785.50 FL	*1,785.50 FL
3	1		*DOOR HANDLE OUTER RH	Not Necessary	398.30 FL	*- FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (\$\$)	4,684.00
					- List Item Discount on L Items 10.00/25.00% (\$\$)	468.40
					Total Parts (\$\$)	4,215.60
						1,339.12

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGE PARTS ,PANEL BEAT WHERE NECESSARY	New	680.00	400.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	890.00	500.00
3	TO CHECK WIRING FUNCTIONS	New	90.00	30.00
4	TO REMOVE UPHDSTERY	New	80.00	80.00
Gross Labour Cost (\$\$)			1,740.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >