

COMFORT TRANSPORTATION PTE LTD
REPAIR ESTIMATE

Vehicle No. : SH 6611E
 Make : HYUNDAI
 Model : IONIQ(G3)

Date: 13.08.21
 Insurance: NTUC
 MVA: MS. LOKE YY

P/P.

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT DOOR LH			RY \$1,797.20
1	FRT DOOR OUTER MOULDING LH			cut \$110.10
1	RR DOOR OUTER MOULDING LH			cut \$125.30
1	ROCKER PANEL OUTER GARNISH LH			RY \$290.00
	SUB TOTAL		235.40	\$2,322.60
	LESS 20%		188.32	\$464.52
	DISCOUNTED TOTAL			\$1,858.08
1	FRT DOOR COMFORT LOGO RH		155	re \$75.00 Nett
1	REAR DOOR COMFORT LOGO RH		101-139.50	re \$80.00 Nett
				\$155.00 Nett
	Labour Charge			
	PANEL BEATING		950	350- \$700.00
	SPRAY PAINTING CHARGE			\$600.00
	TRANSFER OF DOOR			X ⁿⁿ \$120.00
	TOTAL LABOUR		\$1277.82	\$1,300.00
	ESTIMATE TOTAL		2 delays	\$3,313.08

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495799
 'ur' 13/8/21 @ 4pm
 P/P Reunng new parts
 Tanpin @ lkk auto.com
 2 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: