

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE: 13-Aug-21MODEL: Hyundai i40VEHICLE NO.: SH 7117JINSURANCE: NTUC CLSMVA: LIM T S

| PART NO. | DESCRIPTION | QTY | UNIT PRICE | AMOUNT |
|----------|--------------------------|-----|------------|------------|
| | Rear Bumper | 1 | | \$1,106.00 |
| | Rear Bumper Under Cover | 1 | | \$228.00 |
| | Rear Bumper Clips | 10 | \$2.20 | \$22.00 |
| | BootLid Emblem i40 | 1 | | \$67.90 |
| | BootLid Emblem CRDI | 1 | | \$52.40 |
| | SUB TOTAL | | | \$1,476.30 |
| | LESS 20% | | | \$295.26 |
| | DISCOUNTED TOTAL | | | \$1,181.04 |
| | BootLid ComfortDelGro | 1 | | \$20.00 |
| | BootLid 65521111 | 1 | | \$10.00 |
| | Reverse Sensors | 1 | | \$135.70 |
| | SUB S/NETT | | | \$165.70 |
| | LESS 10% | | | \$16.57 |
| | SUB S/NETT TOTAL | | | \$149.13 |
| | Rear Bumper Mat | | | \$50.00 |
| | NETT TOTAL | | | \$50.00 |
| | SPARE PARTS TOTAL | | | \$1,380.17 |
| | Labour Charge | | | |
| | Panel Beating - BootLid | | | \$600.00 |
| | Spray Painting Charge | | | \$600.00 |
| | R/I Reverse Sensors | | | \$120.00 |
| | TOTAL LABOUR | | | \$1,320.00 |
| | ESTIMATE TOTAL | | | \$2,700.17 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphie 97495747
 'WP' 13/8/21 @ 3:40pm
 4/5 Resurvey after repair
 Tanphie 16/8/21
 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: