

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0659/2021/ZK
DATE : 16-Aug-21
WIP : 39914

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 20/8/2021
YOUR INSURED VEH NO : SMW 1747 Y

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS LIM MUI PENG
ADDRESS : BLK 55 HUME AVENUE
#07-06
SINGAPORE 598752
TELEPHONE : HP +65 9624 8735
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900093585-02
VEHICLE NO : **SDK 1237 Y**
MODEL CODE : AUDI A5 2.0 SPORTBACK 2.0 TFSI
MODEL YEAR : 27/4/2019
ENGINE NO : CVK 078768
CHASSIS NO : WAUZZZF54KA036756
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Aug-21
PLACE OF ACCIDENT : ALONG BUKIT TIMAH ROAD OUTSIDE KK HOSPITAL

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED SIDE LABOUR CHARGES FOR ACCIDENT VEHICLE SDK 1237 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGE.	S/N \$ 800.00 280	
2	TO DISMANTLE AND RENEW LHS FRONT DOOR,LHS REAR DOOR AND LHS SILL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00 1650	11000
3	TO RESPRAY LHS FRONT DOOR , DOOR HANDLE . LHS REAR DOOR AND LHS SILL PANEL TRIM	\$ 3,500.00 1650	
TOTAL LABOUR CHARGES SIDE		: \$ <u>7,500.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED REAR LABOUR CHARGES FOR ACCIDENT VEHICLE SDK 1237 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	S/N \$ 360.00	X
2	TO DISMANTLE AND REINSTALL REAR BUMPER. TO REPAIR LHS REAR FENDER. RE-ORGANIZ CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	X
3	TO RESPRAY REAR BUMPER AND LHS REAR FENDER	\$ 2,000.00	550.
4	TO RENEW LHS REAR RIM AND CARRY OUT WHELL ALIGNMENT.	S/N \$ 280.00	✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES (SIDE + REAR)		: \$ 11,932.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDK 1237 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - LH <i>Rep</i>	1	\$ 3,884.00	+
2	FRONT DOOR SEAL - LH <i>Ken</i>	1	\$ 222.00	+
3	FRONT DOOR BONDING <i>Ken</i>	1	\$ 49.00	+
4	FRONT DOOR CLEANING SOULTION <i>Ken</i>	1	\$ 68.00	+
5	FRONT DOOR APPLICATOR <i>3</i>	1	\$ 8.00	+
6	FRONT DOOR CATCH - LH <i>Ken</i>	1	\$ 120.00	+
7	FRONT DOOR TRIM - LH <i>Ken</i>	1	\$ 164.00	✓
8	REAR DOOR - LH <i>Det</i>	1	\$ 3,884.00	✓
9	RAER DOOR SEAL - LH <i>Ken</i>	1	\$ 222.00	✓
10	REAR DOOR BONDING	1	\$ 49.00	?
11	REAR DOOR CLEANING SOULTION	1	\$ 68.00	?
12	REAR DOOR APPLICATOR	1	\$ 8.00	?
13	REAR DOOR ATTACHMENT PART <i>Ken</i>	1	\$ 129.00	+
14	RAER DOOR CATCH	1	\$ 120.00	?
15	SIDE MEMBER TRIM - LH <i>Rep</i>	1	\$ 826.00	+
16	SIDE MEMBER TRIM ATTACHMENT PART <i>Ken</i>	1	\$ 130.00	+
17	ADHESIVE TAPES <i>Ken</i>	1	\$ 212.00	✓
18	REAR ALUMINIUM RIM - LH <i>Ken</i>	1	\$ 1,690.00	✓
19	SUNDRIES		\$ 192.00	?
TOTAL SPARE PARTS			: \$ 12,045.00	
TOTAL LABOUR CHARGES			: \$ 11,932.00	
GRAND TOTAL			: \$ 23,977.00	

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: *Adrian Li*
: *20/08/21.*

:
: *not authorised, 06 days*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT