

BIFROST AUTO PTE LTD

REPAIR ESTIMATE (SUPPLEMENTARY)

DATE: 24-Aug-21

INSURANCE: MSIG

MODEL: MITSUBISHI LANCE EX1.6 AT LED TAIL LAMP

VEHICLE NO.: SLM 5962 E

DESCRIPTION	QTY	UNIT PRICE	NETT PRICE
WASHER TANK DENTED	1	\$81.00	\$81.00
FRONT RH RIM DENTED	1	\$692.00	\$692.00
SUB TOTAL			\$773.00
LESS 10%			\$77.30
DISCOUNTED TOTAL			\$695.70
Labour Charge			
Check Wheel Alignment	1	\$60.00	\$60.00
TOTAL LABOUR			\$60.00
ESTIMATE TOTAL			\$755.70

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.