

ASS. REC. BY: TaufikhREF: CS/CTI21008606/T1c

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. SNM21D204519/C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$94K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SNM 9776M Yr Regn: 2019, JulyType: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota C-HR Hybrid c.c 1797Colour: Black A/C: Insured / Std / NI / NASp. Reading: 43/60 T/Radlo: Insured / Std / NI / NA

Eng/No: _____

C/No: ZYX102069 282

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R18R: 225/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mmR/Bal. 6 mm L/Bal. 6 mmD.O.A. 18/8/21 0230pmSurvey held at Seck. Cars.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/08/21 @ 2.36pm revised to Tan Kah Leong via Merimen.

13/10/21 @ 11.29am Taufikh finalised with Thana final fig \$4420.22, 5 days. (Red \$3567.28, 45%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 25/10 Typist

☐ : Final Report

Date/Time, File Return to?

2) _____

Repair Format: MER-TPLump Sum / L.S. / 4420.22Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$I

Photos

Others

TOTAL



ESTIMATE

DATE OF ACCIDENT : 14/04/2021	
VEHICLE : SMM9776M	
MAKE & MODEL : TOYOTA CHR	
INSURANCE : CHINA TAIPING	
SURVEYOR : LKK	

PARTS			AMOUNT
1.	REAR BUMPER	de ✓	\$ 900
2.	REAR BUMPER DIFFUSER	de ✓	\$ 400
3.	REAR BOOT	b/c ✓	\$ 1200
4.	REAR BOOT GARNISH	cur ✓	\$ 210
5.	REAR END PANEL	Ry ✓	\$ 780
6.	REAR END PANEL TOP COVER	de ✓	\$ 180
7.	BOOT LOCK - UPPER	b/c ✓	\$ 320
8.	BOOT LOCK COVER - UPPER	cur ✓	\$ 100
9.	REAR SUPPORT BEAM	?	\$ 600
	SPECIAL NETT		
1.	BUMPER CLIPS	30 cur ✓	\$ 150
2.	"TOYOTA" EMBLEM	cur ✓	\$ 150



3.	"CHR" EMBLEM	neg	\$ 95
4.	"HYBRID" EMBLEM	neg	\$ 75
5.	WINDSCREEN SEALANT	neg 60	\$ 150
6.	REAR END PANEL SEALANT	x	\$ 100
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer: Signature: _____ Date: _____			
LABOUR			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	700	\$ 1000
2.	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	600	\$ 1500
3.	TO CHECK LIGHTING SYSTEM, WIRING & REWIRE	30	\$ 250
4.	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	60	\$ 220
5.	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	60	\$ 280
6.	TO REMOVE & REINSTALL SENSORS	30	\$ 100
7.	TO REMOVE & REINSTALL REAR WINDSCREEN	120	\$ 200
8.	ANTI RUST TREATMENT	30	\$ 200
Taufm 97495749 / 62563561			PARTS - 25%: \$ 3,517.50
'Wp' 18/8/712 1420			SPECIAL NETT : \$ 720
taufm e lkhants.com			LABOUR : \$ 3,750
P/P Resny before paint			TOTAL : \$ 7,987.50
05 days			7% GST : \$ 559.13
*To check part prices			GRAND TOTAL : \$ 8546.63