



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15662/FAHEEM AHMED KHAN Reg No/Reg Date SMT64632 / 09/07/202 Date In/Mileage / 0 Chassis No GF7W0700365 Engine No 4J11CC5721 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN ( ) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	16/08/2021/ 17:43	BLE	261 / Edwin Caina	14219		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1350.00
RENEW (Fr Portion) FR BUMPER		450 X 1					450 -
REPAIR LHF FENDER							
E PNT88000							3150.00
RENEW (Rr Portion) RR BUMPER , RR END PNL & RR FLR PNL		48 X 450					1800 - 2700
REPAIR TAILGATE , LHR FENDER , RHR FENDER & RR CHASSIS							
E PNT98000							3150.00
RESPRAY RR BUMPER , RR END PNL , TAILGATE , RR FLR PNL , LHR FENDER ,		5 X 350					1750 -
RHR FENDER , RR CHASSIS , FR BUMPER & LHF FENDER							
E PNT88000							120.00
REMOVE & REFIT RR FLR BOARD , TRIM , CARPET & SEAT (photo)							
TO FACILITATE REPAIR							
A 54900099							30.00
CHECK WIRING ELECTRICAL SYSTEM							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
E PNT88000							1000.00
CONDUCT CHASSIS ALIGNMENT-CELETTE BENCH							500 - 3
B WHEELALIGNMENT							120.00
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							50.00
SUPPLY FR NUMBER PLATE WITH CASING							
M SUNDRY							50.00
SUPPLY RR NUMBER PLATE WITH CASING							
E PNT88000							60.00
REMOVE & REFIT REVERSE SENSOR							
M SUNDRY							220.00
SUPPLY REVERSE SENSOR (up)							8 X 780.00
M SUNDRY							
SUPPLY FR CAMERA (Fr Grille)							
M SUNDRY							40.00
APPLY ANTI CORROSION ON AFFECTED AREAS							
M SUNDRY							60.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

To Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15662/FAHEEM AHMED KHAN Reg No/Reg Date SMT6463Z / 09/07/202 Date In/Mileage / 0 Chassis No GF7W0700365 Engine No 4J11CC5721 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN ( ) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	16/08/2021/ 17:43	BLE	261 / Edwin Caina	14219			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
SUPPLY BODY PNL SEALANT								40.00
M SUNDRY								
SUPPLY C&C BADGE								20.00
M SUNDRY								
Sundries								
M	FACE,FR BUMPER	OR			1.00	1048.00	23.00	806.96
M	EXTENSION,FR BUMPER	CUT (Black)			1.00	517.00	23.00	398.09
M	COVER,FR BUMPER	CUT (Silver)			1.00	361.00	23.00	277.97
M	GARNISH,FR BUMPER SIDE	(RH) ? - BR			1.00	48.00	23.00	36.96
M	GARNISH,FR BUMPER SIDE	(LH) - CRA (chrome)			1.00	48.00	23.00	36.96
M	GARNISH,FR BUMPER SIDE	(RH) - BR (chrome)			1.00	220.00	23.00	169.40
M	GARNISH,FR BUMPER SIDE	(LH) - BR (chrome)			1.00	220.00	23.00	169.40
M	GARNISH,FR BUMPER SIDE	(RH) - BR (chrome)			1.00	112.00	23.00	86.24
M	GARNISH,FR BUMPER SIDE	(LH) - BR (chrome)			1.00	112.00	23.00	86.24
M	REINFORCEMENT,FR BUMPER	? x nn			1.00	510.00	23.00	392.70
M	REINFORCEMENT,FR BUMPER	? x nn			1.00	135.00	23.00	103.95
M	GRILLE ASSY,RADIATOR	XNN CUT ? + m			1.00	550.00	23.00	423.50
M	COVER,HEADLAMP SUPT PANEL				1.00	50.00	23.00	38.50
M	FACE,RR BUMPER	OR			1.00	811.00	23.00	624.47
M	BRKT,R/BMPR FACE SIDE,LH	? x nn			1.00	12.00	23.00	9.24
M	BRKT,R/BMPR FACE SIDE,RH	? x nn			1.00	12.00	23.00	9.24
M	REINFORCEMENT,RR BUMPER,LH	? x nn			1.00	79.00	23.00	60.83
M	REINFORCEMENT,RR BUMPER,RH	? x nn			1.00	79.00	23.00	60.83
M	CLIP,FR BUMPER	npc			10.00	4.00	23.00	30.80
M	EXTENSION,RR BUMPER	OR (Silver)			1.00	360.00	23.00	277.20
M	MOULDING,RR BUMPER,LH	npc			1.00	88.00	23.00	67.76
M	MOULDING,RR BUMPER,RH	npc			1.00	88.00	23.00	67.76
M	MOULDING,RR WHEEL ARCH,LH	? x nn			1.00	168.00	23.00	129.36
M	MOULDING,RR WHEEL ARCH,RH	? x nn			1.00	168.00	23.00	129.36
M	REFLECTOR,TAIL LAMP,LH	? x nn			1.00	100.00	23.00	77.00
M	REFLECTOR,TAIL LAMP,RH	? x nn			1.00	100.00	23.00	77.00
M	LAMP ASSY,COMB,RR LH	X			1.00	603.00	23.00	464.31
M	LAMP ASSY,COMB,RR RH	X			1.00	603.00	23.00	464.31

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15662/FAHEEM AHMED KHAN Reg No/Reg Date SM16463Z / 09/07/202 Date In/Mileage / 0 Chassis No GF7W0700365 Engine No 4J11CC5721 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN ( Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	16/08/2021/ 17:43	BLE	261 / Edwin Caina	14219
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M LAMP ASSY, TAIL, LH	X nn	1.00	506.00	23.00	389.62
M LAMP ASSY, TAIL, RH	X nn	1.00	506.00	23.00	389.62
M MARK, OUTLANDER	- nec	1.00	95.00	23.00	73.15
M PANEL, RR END	00 (photo)	1.00	326.00	23.00	251.02
M PANEL, RR END, INR LH	00 x nn	1.00	0.00	23.00	
M PANEL, RR END, INR RH	00 x nn	1.00	146.00	23.00	112.42
M FLOOR, RR	00 (photo) X R	1.00	751.00	23.00	578.27
M TRIM, RR END	CRU	1.00	113.00	23.00	87.01
M BOX, CARGO FLOOR	GR	1.00	204.00	23.00	157.08
M LID, CARGO FLOOR BOX	X nn	1.00	295.00	23.00	227.15
M W/STRIP, TAILGATE OPENING	TAL	1.00	213.00	23.00	164.01
M STRIKER, TAILGATE LATCH	X nn	1.00	20.00	23.00	15.40
M LATCH, TAILGATE	X nn	1.00	385.00	23.00	296.45
M MOULDING, FR BUMPER, LH	nec	1.00	97.00	23.00	74.69
M MOULDING, FR BUMPER, RH	nec	1.00	97.00	23.00	74.69
M MOULDING, FR WHEEL ARCH, LH	1 x nn	1.00	168.00	23.00	129.36
M MOULDING, FR WHEEL ARCH, RH	1 x nn	1.00	168.00	23.00	129.36
M TRIM, RR SHELF	X nn	1.00	672.00	23.00	517.44

SURVEYOR NAME: Steve CLKKJ 17/8/21, 2:00pm

SURVEYOR SIGNATURE: 00- M AL

EXCISE - ?

DATE: PIP

REMARKS: My Bol sy  
15 dgs

LKK Auto Consultants hence notify the Receiver of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Authorized signatory and company stamp

7% GST on Net 19,603.08  
19603.08 1372.22

Total Payable 20,975.30

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.