



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 14.08.2021
Emailed : 21.09.2021, 9.35am *5.02pm*
Date Survey : 17.08.2021

VEHICLE NO : SMT 6463 Z
MODEL : MIT OUTLANDER 2.0
WIP : 14219

Material	:	\$	<u>4,279.63</u>
Labour	:	\$	<u>5,260.00</u>
Sub-Total	:	\$	<u>9,539.63</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>9,539.63</u>
GST 7%	:	\$	<u>667.77</u>
Grand Total	:	\$	<u>10,207.40</u>
Finalise By/Date	:	<u>LOI / 21/09/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 17/08/2021	Cust No/Name KCV15662/FAHEEM AHMED KHAN Reg No/Reg Date SMT6463Z / 09/07/2020 Date In/Mileage 17/08/2021/ 7329 Chassis/Package GF7W0700365 /DC17PT Engine No 4J11CC5721 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN (997) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	21/09/2021/ 16:56	BLE	260 / AiTing	14219

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT DAMAGED PARTS, REPLACE FRONT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 450.00
E PNT88000 REPLACE REAR DAMAGED PARTS, REPLACE REAR BUMPER, REAR END PANEL, REPAIR TAILGATE, REAR FLOOR PANEL, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 1800.00
E PNT98000 RESPRAY ON REAR BUMPER, REAR END PANEL, TAILGATE, REAR FLOOR PANEL, FRONT BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 1750.00
E PNT88000 REMOVE & REINSTALL REAR FLOOR BOARD, TRIMS, CARPETS, & SEATS TO FACILITATE REPAIR				✓ 120.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE				✓ 120.00
E PNT88000 CONDUCT CHASSIS ALIGNMENT - FLOOR BENCH				? 500.00
E PNT88000 REMOVE & REINSTALL REVERSE SENSOR TO FACILITATE REPAIR				✓ 60.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				✓ 40.00
M SUNDRY SUPPLY BODY PANEL SEALANT				✓ 60.00
M SUNDRY SUPPLY C&C BADGE				✓ 40.00
M SUNDRY SUNDRIES				✓ 20.00
S SPECIALISTJOB SUPPLY & REPLACE FRONT LICENSE PLATE WITH FRAME				✓ 50.00
S SPECIALISTJOB SUPPLY ONE SET OF REVERSE SENSOR				✓ 220.00

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 17/08/2021	Cust No/Name KCV15662/FAHEEM AHMED KHAN Reg No/Reg Date SMT6463Z / 09/07/2020 Date In/Mileage 17/08/2021/ 7329 Chassis/Package GF7W0700365 /DC17PT Engine No 4J11CC5721 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN (997) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	21/09/2021/ 16:56	BLE	260 / AiTing	14219

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X FACE,FR BUMPER	1.00	✓ 1048.00	23.00	806.96
X EXTENSION,FR BUMPER	1.00	✓ 517.00	23.00	398.09
X COVER,FR BUMPER	1.00	✓ 361.00	23.00	277.97
X GARNISH,FR BUMPER SIDE	1.00	✓ 48.00	23.00	36.96
X GARNISH,FR BUMPER SIDE	1.00	✓ 48.00	23.00	36.96
X GARNISH,FR BUMPER SIDE	1.00	✓ 220.00	23.00	169.40
X GARNISH,FR BUMPER SIDE	1.00	✓ 220.00	23.00	169.40
X GARNISH,FR BUMPER SIDE	1.00	✓ 112.00	23.00	86.24
X GARNISH,FR BUMPER SIDE	1.00	✓ 112.00	23.00	86.24
X FACE,RR BUMPER	1.00	✓ 811.00	23.00	624.47
X CLIP,FR BUMPER	10.00	✓ 4.00	23.00	30.80
X MOULDING,RR BUMPER,LH	1.00	✓ 88.00	23.00	67.76
X MOULDING,RR BUMPER,RH	1.00	✓ 88.00	23.00	67.76
X MARK,OUTLANDER	1.00	✓ 95.00	23.00	73.15
X PANEL,RR END	1.00	✓ 326.00	23.00	251.02
X TRIM,RR END	1.00	✓ 113.00	23.00	87.01
X BOX,CARGO FLOOR	1.00	✓ 204.00	23.00	157.08
X W/STRIP,TAILGATE OPENING	1.00	✓ 213.00	23.00	164.01
X MOULDING,FR BUMPER,LH	1.00	✓ 97.00	23.00	74.69
X MOULDING,FR BUMPER,RH	1.00	✓ 97.00	23.00	74.69
X BUZZER,KEYLESS OPERATIO,RR	1.00	✓ 91.00	23.00	70.07
X EXTENSION,RR BUMPER	1.00	360 ? 289.00	23.00	222.53
X MARK,THREE-DIA	1.00	61.00	23.00	46.97
X SILENCER,FLOOR	2.00	14.00	23.00	21.56
X EMBLEM MIVEC TECHNOLOGY	1.00	30.00	00.00	30.00
X REAR BUMPER PLATE	1.00	192.00	23.00	147.84

Z TEXT
 AIG OD CLAIM.
 DOA : 14.08.21
 SURVEYOR STEVE LKK 17.08.21
 POLICY NO : 2070103559 REPAIR 15 DAYS

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,279.63	Nett	9,539.63
Labour	4,830.00	7% GST on	667.77
Standard Menu	0.00		
Specialist Job	270.00		
Diagnostics Job	0.00		
Sundry/Others	160.00		
Total(w/o GST)	9,539.63	Total Payable	10,207.40

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys


INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SMT 6463 Z

	<u>Materials</u>	<u>Cost (\$)</u>
1	Buzzer, keyless operatio, RR	91.00 — BR
2	Mark, Three-diamond	61.00 — nec
3	Silencer, floor (x2)	28.00 — nec
4	Emblem mivec technology	30.00 — nec
5	Rear bumper plate (chrome)	192.00 — BT
	Total	402.00
	Less 23% discount	92.46
	Total after discount	309.54
	7% GST	21.67
	Grand total	<u>\$ 331.21</u>

Thank You.

Yours faithfully


LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

WIP: 14219 (ADDITIONAL PARTS CHANGE)

	DATE	TAKEN BY
PHOTO BEFORE PAINT	3/18/21	Steve
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

SURVEYOR: STEVE

Ref No: SMT6AGZ

offer to my prof for unit to see all the line
also the good
to do some by the feel drive

All DTCS

2021.09.06

Setting	
Item	Information
M.U.T.-3 Version	SEW21031-00
V.C.I. Version	B179
Vehicle Information	DBA-GF7W 2020MY

All DTCs

2021.09.06

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCs	
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs	
AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45680040		No DTCs	
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs	
SRS-AIR BAG	ORC_81047302		No DTCs	
Air Conditioner	AC_80080011		No DTCs	
ETACS	ETACS_83040801		No DTCs	
Meter	MTR_84084001		No DTCs	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN	ETACS_83040801		Non-target System	
Power Gate	ETG_92080000		Non-equipped System or Communication Error	
KOS/IMMO/Keyless	KOS_8A880020		No DTCs	

All DTCs

2021.09.06

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
OSS	OSS_9588000B		No DTCs	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCs	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	