



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM21008615/Ura3q2 Date: 18/11/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKT 5559L	Veh. Inspected	SLB 4071R	
Policy No.	GA217874	Coverage (\$)	0.00	
Claim No.	S1M03FPQ	Excess (\$)	0.00	
Assign From		Assign Date	17/08/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ A180 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WDD1760422J445747	Colour	GREY	
Odometer	95739 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	BRIDGESTONE	7 mm	
L/H Front Tyre	225/40 R18	BRIDGESTONE	7 mm	
R/H Rear Tyre	225/40 R18	BRIDGESTONE	7 mm	
L/H Rear Tyre	225/40 R18	BRIDGESTONE	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	16/08/2021	Inspection Date	17/08/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	