CS SMR 21008616/TItC KEF: COE 2025 Jan. ASSIGNMENT GBB7502M YIREGN: 20101 Jun Veh No: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Estimated Cost: OD (TP) WS I TP RES I OD RES I EVA I INV I MV Truck / Trailer or Citroen - Berlingo 1.60 1560. To Inspect Vehicle No: GBB 7502M Insured / Std / NI / NA at Workshop m/s TSL AUTO GARAGE T/Radlo; Insured / Std / NI / NA Sp.Reading SHD 6356T Eng/No: Insured: C/No: Policy No. Gen. Cond: Good / Fair / Poor / Burnt TAX/08/21/2024 Claims No. Steering: Inorder / Jammed / Leaked / Burnt or Excess: Sum Insured: Brake: Ingrder | Jammed | Leaked | Burnt or (Client's Record) Modi: NIL / S/Rim / STD A/Rim or Make of Veh: Tyre Size: (Policy Condition) BS / DUN / EXNOVA / GY / FS / LIZA /MID / OHTSU / PIR / SUMI / Remark: The veh had commenced its repair at the time of inspection. TOYO / YOKO or Rear Front Bal. or Market Value: R/Bal. R/Bal. Consistent? : Yes or No IDAC Accident Rport: UBal. Consistent?: Yes or No L/Bal. GIA / PR Seen: D.O.A. Res.: Yes or No days Est. Repairs: 3 Val.: Yes or No Survey held at Lum Sum: Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision. Person Contacted: Date: Action / Instruction Date / Time GIH uploaded in Views lump sum \$2800. 4days red:8191.72:74% Days Of Repair: 4 Date/Time, File Pass to? : Preli. Report Survey Fee: Resurvey No. of Trip: : Final Report Transportation: Date/Time, File Return to? Add Fee: : Site Insp (\$ Photos : Interview (\$: Tech. Invs (\$ Others Reper Former: : Weel and (\$ Lump Sum / LB A: CF TOTAL

TSL AUTO GARAGE

QUOTATION/ESTIMATE RE: REPAIR VEHICLE ON CITREON BELINGO **VEHICLE NO :GBB7502M** DATE: 12/08/2021

PARTS DESCRIPTION	QTY	UNTIL PRICE	AMOUNT
LIST ITEMS			
1 BONNET 🕅	1	\$1,102.40	\$1,102.40
2 BONNET LOCK K	1	\$145.78	\$145.78
3 FRONT BUMPER &	1	\$980.30	\$980.30
4 FRONT BUMPER TOW COVER ✓	1	\$65.30	\$65.30
5 FRONT BUMPER REINFORCEMENT # 2 ploto	1	\$223.40	\$223.40
6 FRONT BUMPER LOWER GRILLE 4?	1	\$265.45	\$265.45
7 FRONT BUMPER LOWER GRILLE CHROME MOULDING X	1	\$178.64	\$178.64
8 FRONT BUMPER CENTER GRILLE with	1	\$253.15	\$253.15
9 FRONT BUMPER FOG LAMP GARNISH ×	2	\$68.40	\$136.80
10 FRONT BUMPER SIDE RETAINER	2	\$78.64	\$157.28
11 FRONT BUMPER BRACKET *	2	\$112.56	\$225.12
12 FRONT BUMPER TOP PROTECTOR de	2	\$134.67	\$269.34
13 FRONT GRILLE and	1	\$486.56	\$486.56
14 FRONT GRILLE OUTER CHROME w	1	\$282.75	\$282.75
15 FRONT GRILLE BASE ≯	1	\$189.40	\$189.40
16 FRONT SUPPORT PANEL ✓	1	\$786.34	\$786.34
17 FRONT SUPPORT PANEL TOP GARNISH ×	1	\$134.60	\$134.60
18 FRONT HEADLAMP 7. plusto	2	\$715.23	\$1,430.46
19 FRONT HEADLAMP LOWER BRACKET №	2	\$98.40	\$196.80
20 AIR CON CONDENSER ▷	1	\$1,347.60	\$1,347.60
TOTAL:		\$7,649.57	\$8,857.47
LESS 10 % :		\$764.96	\$885.75
TOTAL:		\$6,884.61	\$7,971.72

GBB7502M

S/NETT ITEMS

1 FRONT BUMPER CLIPS

2 FRONT GRILLE CLIPS

3 AIR CON GAS

4 FRONT NUMBER PLATE WITH CASING

1	\$80.0030	\$80.00
1	\$60.00 20	\$60.00

\$100.00 \$100.00 1

\$60.00 \$60.00 × 1

TOTAL:

\$300.00 \$300.00

TOTAL SPARE PARTS:

\$7,184.61 \$8,271.72

LABOUR DESCRIPTION

1 LABOUR FOR PANEL BEATING

2 LABOUR FOR SPRAYPAINTING

3 TO RUST PROOF / TUFF COAT ON REAR ACCIDENT AREAS

LABOUR FOR REMOVE & RENEW AIR CON CONDENER TOP UP GAS

5 WIRING CHECK

AMOUNT

#00 \$1,200.00 #00 \$1,000.00

K \$300.00

× \$160.00

30 \$60.00

TOTAL LABOUR:

\$2,720.00

TOTAL PARTS AND LABOUR:

\$10,991.72

Taufihn 17495749

WP 1/1/12 3pm

1/4/12 3pm

1/4/12 3pm

L/4/12 3p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: