



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Adrian
LKK -
EKGP

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 13/08/2021

Estimated repair cost for vehicle no: SJV3883P TOYOTA PREVIA AERAS 2.4 CVT MR

CHASSIS: JTEGD56M007171943 (2019)

TP Ergo.
Sense.

14/08/2021

S/N	Qty	Items	U/price	Amount	
1	1	REAR TAILGATE Distorted	\$1,950.10	\$1,950.10	1324.
2	1	REAR TAILGATE EMBLEM PREVIA	\$95.20	\$95.20	✓
3	1	REAR TAILGATE EMBLEM TOYOTA	\$92.70	\$92.70	✓
4	1	REAR TAILGATE LOGO	\$96.80	\$96.80	✓
5	1	REAR TAILGATE LOCK & SENSOR	\$495.60	\$495.60	387
6	1	REAR TAILGATE LOCK DETECTOR	\$295	\$295	X
7	1	REAR TAILGATE OUTER CHROME MOULDING	\$270.60	\$270.60	✓
8	1	REAR TAILGATE INNER TRIM BOARD	\$489	\$489	✓
9	1	REAR TAILGATE SHOCK ABSORBER	\$330.30	\$330.30	✓
10	2	REAR TAILGATE STOPPER	\$120.60	\$241.00	X
11	2	REAR TAILGATE SIDE SENSOR	\$375.10	\$750.20	X
12	1	REAR TAILGATE CENTER LAMP	\$405.60	\$405.60	✓
13	2	REAR TAILGATE SIDE LAMP	\$750.50	\$1,501.00	1116.
14	2	REAR TAILGATE SIDE RUBBER STOPPER	\$333.60	\$333.60	X
15	1	REAR TAILGATE WINDSCREEN GLASS MOULDING	\$105.80	\$105.80	✓
16	1	REAR TAILGATE WINDSCREEN GLASS	\$1,350.60	\$1,350.60	1155
17	1	REAR TAILGATE WIPER MOTOR	\$458.60	\$458.60	X
18	1	REAR TAILGATE WIPER ARM	\$135.80	\$135.80	X
19	1	REAR TAILGATE WIPER BLADES	\$55.60	\$55.60	X
20	1	REAR BUMPER	\$847.80	\$847.80	✓
21	2	REAR BUMPER SIDE RETAINER (SMALL)	\$84.30	\$168.60	X
22	2	REAR BUMPER SIDE RETAINER (LONG)	\$92.60	\$185.20	✓
23	2	REAR BUMPER SPONGE	\$105.80	\$211.60	✓
24	2	REAR BUMPER REFLECTOR	\$75.60	\$151.20	X
25	4	REAR BUMPER REVERSE SENSOR	\$495.10	\$1,980.40	370.
26	1	REAR BUMPER REVERSE SENSOR WIRE HARNESS	\$225.20	\$225.20	X
27	1	REAR END PANEL	\$690.30	\$690.30	✓
28	1	REAR END PANEL TOP GARNISH	\$360.40	\$360.40	✓
29	1	REAR END PANEL LOWER GARNISH	\$246.50	\$246.50	✓
30	1	REAR WEATHER STRIPE	\$390.70	\$390.70	✓

31	1	REAR KEYLESS SENSOR <i>New</i>	\$195.80	\$195.80 <i>+</i>
32	1	REAR KEYLESS BUZZER <i>Dmgd</i>	\$135.60	\$135.60 <i>✓</i>
33	2	REAR FENDER INNER TRIM BOARD <i>Delud</i>	\$758.60	\$1,517.20 <i>✓</i>
34	2	REAR BACK SEAT <i>New</i>	\$1,354.60	\$2,709.20 <i>+</i>
35	2	REAR BACK SEAT ELECTRICAL MOTOR <i>New</i>	\$457.20	\$914.40 <i>+</i>
36	1	REAR SPARE TYRE COMPARTMENT PANEL <i>Regis</i>	\$960.10	\$960.10 <i>+</i>
37	2	REAR TAILLAMP <i>LH cracked, RH cut</i>	\$660.30	\$1,320.60 <i>✓ 16030</i>

12343.90
9257.92
7323

TOTAL : \$22,115.00
LESS 25 % \$5,528.75
SUB-TOTAL : \$16,586.25

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>New</i>	\$80.00	\$80.00 <i>30</i>
2	1	REAR END PANEL SEALANT <i>New</i>	\$80.00	\$80.00 <i>60</i>
3	1	REAR END PANEL TOP GARNISH CLIPS <i>New</i>	\$60.00	\$60.00 <i>20</i>
4	2	REAR TAILLAMP CLIPS <i>New</i>	\$20.00	\$40.00 <i>10</i>
5	1	REAR NUMBER PLATE WITH CASING <i>New</i>	\$60.00	\$60.00 <i>+</i>
6	1	REAR END PANEL TOP GARNISH CHROME COVER <i>New</i>	\$280.00	\$280.00 <i>180</i>
7	1	REAR END PANEL TOP GARNISH CHROME LED LIGHT <i>Dmgd</i>	\$180.00	\$180.00 <i>120</i>
8	1	REAR TAILGATE WINDSCREEN GLASS SOLAR FILM <i>New</i>	\$250.00	\$250.00 <i>200</i>
9	2	REAR END PANEL LED LIGHT <i>Dmgd</i>	\$180.00	\$360.00 <i>220</i>
10	1	REAR WINDSCREEN GLASS SEALANT <i>New</i>	\$100.00	\$100.00 <i>60</i>
11	1	REAR REVERSE CAMERA <i>Dmgd</i>	\$580.00	\$580.00 <i>380</i>

1280

TOTAL: \$2,070.00
TOTAL PARTS: \$18,656.25

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS
- 5 LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING

~~\$2,400.00~~ *1200*
~~\$1,800.00~~ *1000*
~~\$60.00~~ *30*
~~\$400.00~~ *80*
~~\$300.00~~ *80*

6	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS	2590	\$150.00 120
7	LABOUR FOR REMOVE & REFIX REAR CARPET & UPHOLSTERY		\$300.00 80.
8	LABOUR FOR REMOVE & RENEW REAR BACK SEAT / TO CHECK DIAGNOSE/ RE-PROGRAMME REAR BACK SEAT		\$300.00 X.

Subtotal :- \$5,710.00

Total:- \$24,366.25

total: 13127.92

4/s: 10 SK.

09 days.

10-SK.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: