3/18/22, 12:03 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21008626/EES3Q2

Date: 18/03/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447

Claimant Vehicle ES786G Insured Vehicle No: SMJ4043T

No:

Date of Loss: 11/08/2021 Nature of Claim: TP Claim No: MFL2021D0003408

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: ES786G

 Make & Model:
 BMW 530I, 2.0 LED NAV (A)
 Engine No:
 13649887B48B20B

 Reg. Date:
 16/06/2017 (Man. Year: 2017)
 Chassis No:
 WBAJA52060G885045

Colour: Black Odometer: 62354 km

Engine Capacity: 1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19 Rear Tyre Size: 245/40 R19
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,850.50	948.38	1,902.12	66.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	750.00	530.00	41.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,130.50	1,698.38	2,432.12	58.88
Approved Total (Overridden) (S\$)		1,350.00		
(S\$)	4,130.50	1,350.00	2,780.50	67.32
+ GST 7.00/7.00% (S\$)	289.14	94.50	194.64	67.32
Nett Amount (S\$)	4,419.64	1,444.50	2,975.14	67.32
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 17/08/2021

Hin Lung Workshop (HQ)

Date Inspected: 19/08/2021 Inspected At: Blk 1008 Bukit Merah Lane 3, #01-20

Singapore 159722

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Mar 2022)

Parts: 143 BMW 530I 2.0 LED NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for ES786G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,384.80 F	*- FL
2	1		*FRONT SIDE RETAINER LH	*Check	25.95 F	*- FL
3	1		*FRONT SIDE RETAINER RH	Not Necessary	25.95 F	*- FL
4	10		*BUMPER CLIPS	Not Necessary	30.00 F	*- FL
5	1		*FRONT IMPACT ABSORBER	Not Necessary	75.00 F	*- FL
6	1		*FRONT FENDER LH	Dented	938.00 F	*938.00 FL
7	1		*FRONT FENDER EMBLEM LH	Necessary	60.30 F	*60.30 FL
8	1		*FRONT FENDER MOULDING LH	*Check	64.60 F	*- FL
9	1	oart. L=ListIter	*FRONT SENSOR	*Check	245.90 F	*-FL
Г-ГІ	iricriise p	Jart. L-Listitei	iiDisc.	Sub Total (S\$)	2,850.50	998.30
			- List Item Discou	nt on L Items 0.00/5.00% (S\$)	0.00	49.92
				Total Parts (S\$)	2,850.50	948.38
			Report was unsubmitte	d during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REPLACE NEW PARTS ,REMOVE/REFIT ALL ATTACHMENT PARTS TO FACILITATE REPAIR	New	600.00	300.00
2	SPRAY PAINT ON THE EFFECTED AREAS WITH 2K PAINT	New	600.00	400.00
3	CHECK WIRING AND PROPER FUNCTIONING	New	80.00	50.00
	Gross Labour Cost (S\$)		1,280.00	750.00
Report was unsubmitted during this print-out.				

< END OF ESTIMATES >