

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:

Our Ref : 0725/08/21

M/s : INDIA INTERNATIONAL INSURANCE P.LTD

64 CECIL STREET

#04/#05 IOB BUILDING

SINGAPORE 049711

Attn : MOTOR CLAIM DEPARTMENT

Page: 1

Date: 17/08/2021

Dear Sir/Madam,

ACCIDENT REPAIR ON : ES786G - BMW 530I 0
INSURED : ABEDEEN ABDULKADER TYEBALLY
DATE OF ACCIDENT : 11/08/2021
YOUR INSURED VEH NO: SMJ4043T

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

			S\$	S\$	S\$
<u>REPLACEMENT OF PARTS</u>					
1	FRONT BUMPER	X R	1 @	1,384.80	1,384.80
2	FRONT SIDE RETAINER LH	?	1 @	25.95	25.95
3	FRONT SIDE RETAINER RH	X	1 @	25.95	25.95
4	BUMPER CLIPS	X	10 @	3.00	30.00
5	FRONT IMPACT ABSORBER	X	1 @	75.00	75.00
6	FRONT FENDER LH	DO (A/m/m)	1 @	938.00	938.00
7	FRONT FENDER EMBLEM LH	APC	1 @	60.30	60.30
8	FRONT FENDER MOULDING LH	?	1 @	64.60	64.60
9	FRONT SENSOR	?	1 @	245.90	245.90
Total					2,850.50

LABOUR CHARGES

1	REPLACE NEW PARTS, REMOVE/REFIT ALL	600.00	300
1	ATTACHMENT PARTS TO FACILITATE REPAIR		
1			
2	SPRAY PAINT ON THE EFFECTED AREAS	600.00	400
2	WITH 2K PAINT.		
2			
3	CHECK WIRING AND PROPER FUNCTIONING	80.00	50
Nett Total Before GST			4,130.50

Yours faithfully,


(Workshop Manager)

LPK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date: