



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2107228

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 19/10/2021
Reference CC4/FCI21008638/R1ra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLJ 2268L
Insured Veh. SMX 2630M
Claim No. D21001691MFZH/1
Policy No. D-20096383MFZH
Accident Date 02/06/2021
Inspection Date 19/08/2021

Description	Total
Survey Inspection	262.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	262.00
GST (7%)	18.34
Grand Total	280.34

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21008638/R1ra3q2	
			Date: 19/10/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMX 2630M	Veh. Inspected	SLJ 2268L
	Policy No.	D-20096383MFZH	Coverage (\$)	0.00
	Claim No.	D21001691MFZH/1	Excess (\$)	0.00
	Assign From	ESTHER LIM	Assign Date	17/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 216D GRAN TOURER	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WBA2E320005B45549	Colour	BROWN
	Odometer	27333 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R17	MICHELIN	6 mm
	L/H Front Tyre	205/55 R17	MICHELIN	6 mm
	R/H Rear Tyre	205/55 R17	MICHELIN	6 mm
	L/H Rear Tyre	205/55 R17	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/06/2021	Inspection Date	19/08/2021
	Survey held at	BIS AUTOMOBILES PTE LTD 30 TEBAN GARDENS CRESCENT, SINGAPORE 608927		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 2268L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LEFT PROTECT (SN)	NOT NECESSARY	10.69	-
1	RIGHT PROTEC (SN)	NOT NECESSARY	10.69	-
1	BUMPER TRIM (SN)	SCRATCHED	998.12	998.12
1	SET OF MOUNT (SN)	NECESSARY	57.95	57.95
			1,077.45	1,056.07
	<u>LABOUR</u>			
	REPLACE WITH REALIGN REAR BUMPER BY PANEL BEATING.		2,400.00	900.00
	VEHICLE DIAGNOSIS -CARRYING OUT THE ABL.		754.00	599.95
	SPRAY PAINTING FOR REAR BUMPER.		900.00	800.00
			4,054.00	2,299.95
	GRAND TOTAL		5,131.45	3,356.02
	RECOMMENDED COST OF REPAIRS			3,356.02

Report Ref No. CC4/FCI21008638/R1ra3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLJ 2268L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLJ 2268L

RE-INSPECTION

