

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: AXA	DATE	: 17/08/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: XD6389J		
MODEL	: MIT FV51		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 14-Aug-21
		TIME	: 09:45HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT CONCR PANEL LH <i>rehd</i>	1	\$ 1,533.20	\$ 1,533.20
2	CABIN ASSY <i>Repair</i>	1	\$ 32,000.00	\$ 32,000.00
3	CABIN GLASS <i>cut</i>	1	\$ 655.80	\$ 655.80
4	FRONT DOOR <i>Dented</i>	1	\$ 5,855.30	\$ 5,855.30
5	FRONT DOOR WINDOW GLASS <i>cut</i>	1	\$ 890.20	\$ 890.20
6	FRONT DOOR WINDOW GLASS CHANNEL <i>cut</i>	1	\$ 255.30	\$ 255.30
7	FRONT DOOR SIGNAL LAMP <i>cracked</i>	1	\$ 120.00	\$ 120.00
8	FRONT DOOR OUTER HANDLE <i>cut</i>	1	\$ 355.20	\$ 355.20
9	FRONT DOOR OUTER HANDLE HOUSING <i>cut</i>	1	\$ 110.60	\$ 110.60
10	FRONT DOOR SMALL GLASS CHANNEL <i>new</i>	1	\$ 255.30	\$ 255.30
11	FRONT DOOR SMALL GLASS <i>cut</i>	1	\$ 680.00	\$ 680.00
12	FRONT DOOR BOTTOM RUBBER <i>new</i>	1	\$ 140.00	\$ 140.00
13	FRONT STEP PANEL UPPER <i>2</i>	1	\$ 822.30	\$ 822.30
14	FRONT STEP PANEL LOWER <i>1</i>	1	\$ 720.00	\$ 720.00
15	FRONT STEP PANEL COVER <i>1</i>	1	\$ 420.20	\$ 420.20
16	FRONT FENDER <i>Repair</i>	1	\$ 1,355.20	\$ 1,355.20
17	FRONT FENDER BOTTOM RUBBER <i>new</i>	1	\$ 160.00	\$ 160.00
18	FRONT BUMPER <i>new</i>	1	\$ 3,550.00	\$ 3,550.00
19	SIDE MIRROR STAND <i>Best</i>	1	\$ 588.30	\$ 588.30

20	SIDE MIRROR TOP <i>new</i>	1	\$ 190.00	\$ 190.00
21	SIDE MIRROR CENTRE <i>Missing</i>	1	\$ 230.00	\$ 230.00
22	SIDE MIRROR BELOW <i>could</i>	1	\$ 255.30	\$ 255.30

10971

8228.25

TOTAL PRICE \$ 51,142.20

LESS 10% \$ 5,114.22

SUB TOTAL PRICE \$ 46,027.98

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR GLASS SESLANT <i>new</i>	1	\$ 120.00	\$ 120.00

TOTAL \$ 120.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 4,000.00	700	
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 2,200.00	800	
3	TO SPRAY TUFF COAT	\$ 250.00	60	
4	WIRING, BULB CHECKING	\$ 280.00	30	
5	REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 180.00	80	
6	TP REMOVE AND REFIX FRONT DOOR MECHANISM	\$ 80.00	50	
7	TO REMOVE AND REFIX FRONT DOOR GLASS	\$ 80.00	50	
8	TO REMOVE AND REFIX FRONT DOOR GLASS (SMALL)	\$ 180.00	40	

TOTAL

\$7,250.00

TOTAL PARTS COST : \$ 46,147.98

TOTAL LABOUR COST : \$ 7,250.00

TOTAL REPAIR COST : \$ 53,397.98

APPROVED DETAILS

EXCESS

NO. OF WORKING DAYS:

RE-SURVEY

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L

H/S 18/08/21

05 days

total: 10098.25

H/S: 8K