

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21008642/AGS3Q2  
**Date:** 01/12/2021**REFERENCE**

|                              |                                      |                             |               |
|------------------------------|--------------------------------------|-----------------------------|---------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100370479-07 |
| <b>Claimant Vehicle No :</b> | SMZ4930Z                             | <b>Insured Vehicle No :</b> | ER5115R       |
| Date of Loss:                | 05/08/2021                           | Nature of Claim:            | TP            |
|                              |                                      | Claim No:                   | 0739577482SG  |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMZ4930Z</b>                   |             |                   |
| Make & Model:               | TOYOTA CAMRY, 2.0 (A)             | Engine No:  | A25A0A32347       |
| Reg. Date:                  | 29/04/2021 (Man. Year: 2020)      | Chassis No: | JTNB23HK003076662 |
| Colour:                     | White                             | Odometer:   | 14556 km          |
| Engine Capacity:            | 2487 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 215/55 R17    | Rear Tyre Size:  | 215/55 R17    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 4,220.05          | 2,809.65          | 1,410.40          | 33.42         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 1,550.00          | 450.00            | 1,100.00          | 70.97         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>5,770.05</b>   | <b>3,259.65</b>   | <b>2,510.40</b>   | <b>43.51</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>2,600.00</b>   |                   |               |

|                                    |  |                 |                 |                 |              |
|------------------------------------|--|-----------------|-----------------|-----------------|--------------|
| <b>Nett Amount (S\$)</b>           |  | <b>5,770.05</b> | <b>2,600.00</b> | <b>3,170.05</b> | <b>54.94</b> |
| <b>Global Sum Settlement (S\$)</b> |  |                 | <b>0.00</b>     |                 |              |

INSPECTION

|                             |            |               |                                                                                                                  |
|-----------------------------|------------|---------------|------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 17/08/2021 |               |                                                                                                                  |
| Date Inspected:             | 17/08/2021 | Inspected At: | Hua Meng Spray Painting Workshop (HQ)<br>No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit<br>Singapore 417883 |
| Estimated Period of Repair: | 3.0 days   |               |                                                                                                                  |

|                  |             |                 |               |
|------------------|-------------|-----------------|---------------|
| <b>Adjuster:</b> | ADRIAN LING | <b>Manager:</b> | Chong Pui Lin |
|------------------|-------------|-----------------|---------------|

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                 | Deformed      | 866.20 FL   | *866.20 FL   |
| 2   | 2   |          | *FRONT BUMPER SIDE HOLDER     | Not Necessary | 379.00 FL   | *- FL        |
| 3   | 1   |          | *FRONT BUMPER RH SIDE GARNISH | Not Necessary | 278.00 FL   | *- FL        |
| 4   | 1   |          | *FRONT RH HEADLAMP            | Cut           | 3,395.00 FL | *2,840.00 FL |
| 5   | 1   |          | *SET FRONT BUMPER CLIPS       | Necessary     | 60.00 FS    | *30.00 FS    |
| 6   | 1   |          | *FRONT BUMPER RH SENSOR       | Not Necessary | 471.40 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                   |          |          |
|---------------------------------------------------|----------|----------|
| Sub Total (\$)                                    | 5,449.60 | 3,736.20 |
| - List Item Discount on L Items 25.00/25.00% (\$) | 1,229.55 | 926.55   |
| Total Parts (\$)                                  | 4,220.05 | 2,809.65 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                        | Lab.Type | Repairer's      | Amount        |
|---------------------------------|----------------------------------------------------|----------|-----------------|---------------|
| <u>Labour Items</u>             |                                                    |          |                 |               |
| 1                               | REMOVE & REINSTALL FRONT SENSOR                    | New      | 150.00          | 50.00         |
| 2                               | REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT | New      | 800.00          | 200.00        |
| 3                               | RESPRAY PAINTING                                   | New      | 600.00          | 200.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                                    |          | <b>1,550.00</b> | <b>450.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >