

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TPAIG Jasper.

Name : LIM CHIN SIANG
Vehicle No : SMZ 4930 Z

Make/Model : TOYOTA CAMRY

Accident date : 05.08.2021

JTNB23HK003076662

No	DESCRIPTION	Qty	Amount (S\$)
----	-------------	-----	--------------

List Items

1	Front bumper <i>Dehind</i>	1	\$ 866.20 ✓
2	Front bumper side holder @ \$189.50 <i>He m</i>	2	\$ 379.00 X
3	Front bumper RH side garnish <i>He m</i>	1	\$ 278.00 X
4	Front RH headlamp <i>ut</i>	1	\$ 3,395.00 <i>2840</i>
			\$ 4,918.20
Less 25% Disc			\$ 1,229.55
Total			\$ 3,688.65

Special Nett Items

1	Front bumper clips (1 set) <i>New</i>	1	\$ 60.00 <i>30</i>
2	Front bumper RH sensor <i>New</i>	1	\$ 471.40 X
Total			\$ 531.40

Labour Cost

1	Remove & reinstall front sensor	\$ 150.00 <i>50</i>
2	Remove ,replace & repair consistent to the accident	\$ 800.00 <i>200</i>
3	Respray painting	\$ 600.00 <i>200</i>
Total		\$ 1,550.00

Grand Total \$ 5,770.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3259.65

2/s: 26k.

03 days.