

# 趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Not Authorised  
L1 Reg # 55504  
Performing After Paint  
Today

To: Lonpac Insurance Pte Ltd

Policy No: \_\_\_\_\_

17.08.2021

Date: \_\_\_\_\_

Accident Date : 16.08.2021

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Honda Vezel" Reg. No SMQ4144Z Claiming Against Your Insured Soon Hin Foods Pte Ltd			
1pc	Front Door LH		R 1,135.00 ✓
1pc	Front Door Sticker		nc 36.00 ✓
1pc	Front Door Inner Lock		R 275.00 X
1pc	Front Door Top Rubber Seal (Vertical)		nc 36.00 ✓
1pc	Front Door Lower Rubber Seal		nc 30.00 ✓
10pcs	Front Door Trim Board Clips	4.00	nc 40.00 X
1pc	Front Door Outer Handle		nc 282.00 ✓
1pc	Front Door Outer Handle End Cover		nc 65.00 ✓
1pc	Front Door Glass Regulator/Motor		nc 499.00 ✓
1pc	Door "B" Pillar		R 1,030.00 ✓
1pc	Rear Door LH		R 977.00 ✓
1pc	Rear Door Outer Vertical Rubber Seal		nc 36.00 ✓
1pc	Rear Door Sticker		nc 33.50 ✓
1pc	Rear Door Weatherstrip	49.50/n	nc 99.00 ✓
1pc	Rear Door Top Rubber Seal (Vertical)		nc 36.00 ✓
1pc	Rear Door Lower Rubber Seal		nc 40.60 ✓
1pc	Rear Door Inner Lock		nc 220.00 ✓
1pc	Rear Door Trim Board		nc 665.00 ✓
10pcs	Rear Door Trim Board Clips	4.00	nc 16.00 ✓
1pc	Rear Door Glass Regulator/Motor		R 496.00 ✓
1pc	Rear Door Glass Guide		nc 102.00 ✓
1pc	Rear Door Lower Chip Resistant Sticker		nc 40.00 ✓
1pc	Rear Door Lower Stopper		nc 11.00 ✓
1pc	Rear Door Arrestor		nc 60.00 X
1pc	Rear Door Top Hinge		R 50.00 ✓
1pc	Rear Door Lower Hinge		R 50.00 ✓
1pc	Rocker Panel Skirt LH		nc 392.00 ✓
10pcs	Rocker Panel Skirt Clips	4.00	nc 40.00 ✓
1pc	Rear Fender Protector LH	4.00	nc 40.00 ✓
10pcs	Rear Fender Protector Clips		nc 205.00 X
1pc	Rear Bumper Cover LH	4.00	nc 48.00 X
12pcs	Rear Bumper Clips		nc 276.00 X
1pc	Rear Bumper Wheel Bearing		
Less 20%			7,541.10
			1,508.22
			6,032.88
C/F			6,032.88



# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Lonpac Insurance Pte Ltd

Policy No: Third Party

Date: 17.08.2021

Accident Date : 16.08.2021

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Honda Vezel" Reg. No SMQ4144Z Claiming Against Your Insured Soon Hin Foods Pte Ltd		
		B/F	6,032.88
	Front Door Inner Insulation		nn 180.00 SN X
	Sticker - Car Info		nn 50.00 SN X
	Rear Door Inner Insulation		nn 180.00 SN X
	Rear Wheel Rim		nn 850.00 SN X
	To Conduct Electrical Check, Focus Headlamp		30.00 201
	To Dismantle / Transfer 2x Door Fittings / Ancillary Accessories	150.00	300.00 1201
	To Dismantle Rear Seat, Floor Carpet to Facilitate Repair		120.00 801
	To Dismantle / Refit Front Pax Seat Belt For Welding Pillar Panel, & Fault Code Erasure		150.00 401
	To Supply Door Pillar Body Sealant		60.00 301
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		150.00 901
	To Dismantle / Hi Pressure Press / Replace Wheel Bearing		nn 120.00 X
	To Conduct Computerize Wheel Alignment Test		nn 80.00 X
	To Conduct High Speed Balancing		nn 80.00 X
	Labour Charge - Panel Beating, Repairing of Floor Panel, Rear Fender, Rocker Panel, Inner Panel etc. Cnt, Weld Door "B" Pillar and Part Replacement		1,200.00 7001
	To Respray Affected Areas		nn 120.00 X
			nn 80.00 X
			nn 80.00 X
			1,200.00 7001
			1,300.00 8001
			10,882.88

KK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date: