



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7622S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER COVER	TO REPAIR SEE LABOUR	459.40	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,768.30	-
1	REAR BUMPER SIDE BRACKET LH	NOT NECESSARY	55.80	-
	LESS 20% DISCOUNT		-461.10	-4.40
			1,844.40	17.60
	<u>SPECIAL NETT ITEMS</u>			
1	REAR DOOR COMFORTDELGRO APPS STICKER LH (SN)	NECESSARY	80.00	80.00
1	REAR FENDER PETROL STICKER (SN)	NECESSARY	15.00	15.00
1	REAR BUMPER RUBBER MAT (SN)	NOT NECESSARY	50.00	-
			145.00	95.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER COVER AND REAR FENDER LH.		950.00	700.00
	SPRAY PAINTING CHARGE.		850.00	750.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		120.00	60.00
			1,980.00	1,510.00
	GRAND TOTAL		3,969.40	1,622.60
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,622.60

Report Ref No. NS/INC21008653/T1tcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.