

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SH 7622S

Make : HYUNDAI

Model : IONIQ(G3)

Date: 16/08/2021

Insurance: NTUC

MVA: MS. LOKE YY

P1P

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			<i>RY</i> \$459.40
10	REAR BUMPER CLIPS			<i>hal</i> \$22.00
1	REAR FENDER LH			<i>RY</i> \$1,768.30
1	REAR BUMPER SIDE BRACKET LH			<i>nn X</i> \$55.80
	<b>SUB TOTAL</b>			\$2,305.50 <i>22</i>
	<b>LESS 20%</b>			\$461.10
	<b>DISCOUNTED TOTAL</b>			<b>\$1,844.40</b> <i>17.60</i>
1	REAR DOOR COMFORTDELGRO APPS STICKER LH			<i>nel</i> \$80.00 <i>Nett</i>
1	REAR FENDER PETROL STICKER			<i>nc</i> \$15.00 <i>Nett</i>
1	REAR BUMPER RUBBER MAT			<i>nn X</i> \$50.00 <i>Nett</i>
				<b>\$65.00</b> <i>95</i>
	<b>Labour Charge</b>			
	PANEL BEATING			<i>500</i> \$700
	SPRAY PAINTING CHARGE			<i>6750</i> \$950.00
	TUFF KOTE			<i>6750</i> \$850.00
	REMOVE/ REFIX CUSHION & UPHOLSTERY REAR			<i>nn X</i> \$60.00
	<b>TOTAL LABOUR</b>			<i>60</i> \$120.00
				<b>\$1,980.00</b> <i>1510</i>
	<b>ESTIMATE TOTAL</b>			<b>\$3,889.40</b>
				<b>\$1622.60</b> <i>3 days</i>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97415249  
 WP? 46/8/21 E 420pm  
 P/P Resurvey new parts  
 Tanpin C/Chant  
 3 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: