



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL C/O : KELVIN CHIA PARTNERSHIP 6 TEMASEK BOULEVARD 29TH FLOOR SUNTEC TOWER FOUR SINGAPORE 038986			Ref: CS/LAW21008659/Dtf3e2 Date: 03/12/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	XD 8817C	Veh. Inspected	SKL 8223C	
Policy No.	CMTD2001923	Coverage (\$)	0.00	
Claim No.	2020001606.Sompo	Excess (\$)	0.00	
Assign From	TEO YI XUAN	Assign Date	18/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180 COUPE	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WDD2053402F827462	Colour	SILVER	
Odometer	46843 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/30 R19	FALKEN	5 mm	
L/H Front Tyre	275/30 R19	FALKEN	5 mm	
R/H Rear Tyre	275/30 R19	FALKEN	5 mm	
L/H Rear Tyre	275/30 R19	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	26/06/2020	Inspection Date	10/09/2021	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			15 Working Days	