



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT21002507	Page	1
Registration No	: SKL7829L	Date	: 13. Aug 2021	Customer No.	: WZI007
Chassis No	: JHMRC1890GC205304	Svc Advisor	: ANIKKA LAI SWEE KAM	Engine No	: K24W72012471
Model	: ODYSSEY 2.4 EXV-S 16YM	Date Time	: 13. Aug 2021 8:38:20 AM	Surveyor Name	:
Owner's Name	: MOGILAN S/O MOHAN	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 11/8/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST	
	TP DIRECT SETTLEMENT (J/NO:) OWNER: MOGILAN S/O MOHAN OWNER INSURER: LIBERTY ACC DATE: 11/08/2021 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INSURANCE TP VEH: SLS9308L							
04636-T6A-J22ZZ	PANEL SET,R.RR.OUTSIDE <i>bt</i>	1	997.30	25	747.97	52.36	800.33	
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>me</i>	2	10.30	25	15.45	1.08	16.53	
73810-T6A-003	SEALR.QUARTER GLASS <i>me</i>	1	37.50	25	28.12	1.97	30.09	
91501-SMA-003	CLIP AQTR. <i>me</i>	1	3.20	25	2.40	0.17	2.57	
91501-SYA-000	CLIPQUARTER WINDSHIELD A <i>me</i>	1	4.10	25	3.07	0.21	3.28	
91513-S70-003	CLIPL <i>me</i>	1	4.10	25	3.07	0.21	3.28	
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>me</i>	1	60.00		60.00	4.20	64.20	
72915-T6A-003	MOLDING ASSYR.QTR WINDSHIELD <i>me</i>	1	117.00	25	87.75	6.14	93.89	
67510-T6A-J00ZZ	PANEL COMPR.SLIDE DOOR <i>bt</i>	1	1067.00	25	800.25	56.02	856.27	
75313-T6A-J11ZD	GARNISH ASSYR.SLIDE DOOR LWR <i>me</i>	1	290.10	25	217.57	15.23	232.80	
72721-T6A-003	GARNISHR.RR.SLIDE DOOR PILLAR ?	1	49.10	25	36.82	2.58	39.40	
74551-T6A-000	FENDERR.RR.INNER ?	1	124.00	25	93.00	6.51	99.51	
74475-T6A-000	STRAKER.RR. <i>MIS</i>	1	12.90	25	9.67	0.68	10.35	
04715-T6A-900ZZ	FACERR.BUMPER <i>repair</i>	1	606.10	25	454.57	31.82	486.39	
42700-T6A-J81	DISK ALUMINIUM WHEEL 17X7J <i>see</i>	1	975.70	25	731.77	51.22	782.99	
					Sum Item	3291.48	230.40	3,521.88
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60	
					Sum Ext. Service	180.00	12.60	192.60

Printed on 13/8/2021 3:55:57 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

Name Of Repair:

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT21002507	Page	2
Registration No	: SKL7829L	Date	: 13. Aug 2021	Customer No.	: WZ1007
Chassis No	: JHMRC1890GC205304	Svc Advisor	: ANIKKA LAI SWEE KAM	Engine No	: K24W72012471
Model	: ODYSSEY 2.4 EXV-S 16YM	Date Time	: 13. Aug 2021 8:38:20 AM	Surveyor Name	:
Owner's Name	: MOGILAN S/O MOHAN	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 11/8/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BA02R	REMOVE & REFIX REVERSE SENSORS-4 PCS (N)	1	150.00		150.00	10.50	160.50
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	650.00		650.00	45.50	695.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00		450.00	31.50	481.50
BG52R	REPLACE RR. R QTR GLASS.(N)	1	350.00		350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR SEAT COMPARTMENT LININGS	1	650.00		650.00	45.50	695.50
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BKFE22R	CUT & RENEW RR R FENDER. STRAIGHTEN INNER PANEL	1	2500.00		2500.00	175.00	2675.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	2500.00		2500.00	175.00	2675.00
Sum Labor					7450.00	521.50	7,971.50

Survey By	<u>Rasul - Hp 90010068</u>	Total Amount	10,921.48	764.50	11,685.98
Date & Time	<u>18/08/21 @ 16:15</u>	Total (Inclusive of GST)	11,685.98		
Excess	<u>6 days</u>				
Status					
Signature	<u>[Signature]</u>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Printed on 13/8/2021 3:55:57 PM
 This is a computer generated invoice. No signature is required.
 Part prices are subjected to change without notice.
 The above estimated cost of repair do not include any unforeseen damages.
 GST Amount is calculated from individual line(s).
 An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.
 However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.