



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0125625 / MOGILAN S/O
Chassis No: JHMRC1890GC205304
License No: SKL7829L
Mileage: 87503
Engine No: K24W72012471

Document No: SVO21042669
Printed By: ANIKKALAI
Order Date: 18. August 2021
Order Time: 4:22:34 PM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	SUPPLEMENTARY PART						
35070	TAPESLIDE.DR.REFLECTOR. nec ✓	1	5.40	25	4.05	0.28	4.33
			SUM EXCESS:		4.05	0.28	4.33
67821-T6A-305ZA	TAPE SETR.RR.DOOR SASH INNER nec ✓	1	60.90	25	45.67	3.20	48.87
72925-T6A-003	MOLDINGR.SLIDE DOOR RETAINER nec ✓	1	103.00	25	77.25	5.41	82.66
74410-T6A-J01ZQ	GARNISH ASSY R,WHEEL ARC mis ✓	1	38.40	25	28.80	2.02	30.82
			SUM PARTS:		151.72	10.63	162.35
			TOTAL SGD		155.77	10.91	166.68
			Total Payable (SGD)				166.68

GST Amount is calculated from individual line(s)

HONDA

QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SKL7829L

Chassis No : JHMRC1890GC205304

Model : ODYSSEY 2.4 EXV-S 16YM

Owner's Name : MOGILAN S/O MOHAN

Ins Policy No. :

Date of Accident : 11/8/2021

Document No. : SQT21002507 Page 2

Date : 13. Aug 2021

Customer No. : WZ1007

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : K24W72012471

Date | Time : 13. Aug 2021 8:38:20 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	100.00	30 /	100.00	7.00	107.00
BA02R	REMOVE & REFIX REVERSE SENSORS-4 PCS (N)	1	150.00	80 /	150.00	10.50	160.50
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	650.00	325 /	650.00	45.50	695.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00	350 /	450.00	31.50	481.50
BG52R	REPLACE RR. R QTR GLASS.(N)	1	350.00	280 /	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR SEAT COMPARTMENT LININGS	1	650.00	/	650.00	45.50	695.50
BOJSE	BODY JOINT SEALANT.	1	100.00	80 /	100.00	7.00	107.00
BKFE22R	CUT & RENEW RR R FENDER. STRAIGHTEN INNER PANEL @ 650	1	2500.00	1950 /	2500.00	175.00	2675.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P) @ 520	1	2500.00	1560 /	2500.00	175.00	2675.00
Sum Labor					7450.00	521.50	7,971.50

Survey By Rasul - Hp 90010068

Date & Time 18/08/21 @ 1615

Excess 6 days

Status _____

Signature [Signature] Res before paint

Total Amount 10,921.48 764.50 11,685.98

Total (Inclusive of GST) 11,685.98

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 13/8/2021 3:55:57 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SKL7829L
Chassis No : JHMRC1890GC205304
Model : ODYSSEY 2.4 EXV-S 16YM
Owner's Name : MOGILAN S/O MOHAN
Ins Policy No. :
Date of Accident : 11/8/2021

Document No. : SQT21002507
Date : 13. Aug 2021
Customer No. : WZI007
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : K24W72012471
Date | Time : 13. Aug 2021 8:38:20 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST	
	TP DIRECT SETTLEMENT (J/NO:) OWNER: MOGILAN S/O MOHAN OWNER INSURER: LIBERTY ACC DATE: 11/08/2021 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INSURANCE TP VEH: SLS9308L							
04636-T6A-J2ZZZ	PANEL SET,R.RR.OUTSIDE <i>4/</i>	1	997.30	25	747.97	52.36	800.33 ✓	
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>re</i>	2	10.30	25	15.45	1.08	16.53 ✓	
73810-T6A-003	SEALR.QUARTER GLASS <i>re</i>	1	37.50	25	28.12	1.97	30.09 ✓	
91501-SMA-003	CLIP AQTR. <i>re</i>	1	3.20	25	2.40	0.17	2.57 ✓	
91501-SYA-000	CLIPQUARTER WINDSHIELD A <i>re</i>	1	4.10	25	3.07	0.21	3.28 ✓	
91513-S70-003	CLIPL <i>re</i>	1	4.10	25	3.07	0.21	3.28 ✓	
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>re</i>	1	60.00		60.00	4.20	64.20 ✓	
72915-T6A-003	MOLDING ASSYR.QTR WINDSHIELD <i>re</i>	1	117.00	25	87.75	6.14	93.89 ✓	
67510-T6A-J00ZZ	PANEL COMPR.SLIDE DOOR <i>bt</i>	1	1067.00	25	800.25	56.02	856.27 ✓	
75313-T6A-J11ZD	GARNISH ASSYR.SLIDE DOOR LWR <i>re</i>	1	290.10	25	217.57	15.23	232.80 ✓	
72721-T6A-003	GARNISHR.RR.SLIDE DOOR PILLAR <i>? Xsr</i>	1	49.10	25	36.82	2.58	39.40	
74551-T6A-000	FENDERR.RR.INNER <i>Xsr</i>	1	124.00	25	93.00	6.51	99.51	
74475-T6A-000	STRAKER.RR. <i>M/S</i>	1	12.90	25	9.67	0.68	10.35 ✓	
04715-T6A-900ZZ	FACERR.BUMPER <i>repair</i>	1	606.10	25	454.57	31.82	486.39	
42700-T6A-J81	DISK ALUMINIUM WHEEL 17X7J <i>seal</i>	1	975.70	25	731.77	51.22	782.99 ✓	
					Sum Item	3291.48	230.40	3,521.88
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60	
					Sum Ext. Service	180.00	12.60	192.60

Printed on 13/8/2021 3:55:57 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.