

ATDELGRO ENGINEERING PTE LTD

ESTIMATE*

NO SHA3394T
HYUNDAI
IONIQ

DATE: 16. August 2021
MVA JUMANI
DOA: 17. Aug. 2021

NTUC (PIP)

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRT BUMPER ASSY			\$430.90
10	FRT BUMPER CLIPS			\$22.00
1	FRT FENDER LH			\$588.80
1	HEADLAMP ASSY LH			\$1,993.65
1	FRT FENDER EMBLEM LH			\$26.60
1	DAY LIGHT LAMP ASSY LH			\$642.50
1	FRT BUMPER BRACKET LH			\$35.00
<p><i>Cup</i> <i>Modeling fct bumper LH 93-45</i> <i>bro</i></p>				
SUB TOTAL				\$3,739.45
LESS 25% 20%				\$747.89
DISCOUNTED TOTAL				\$2,991.56
<div> <p>Labour Charge</p> <p>PANEL BEATING</p> <p>SPRAY PAINT</p> <p>CHECK WIRING</p> <p>TUFF KOTE</p> </div>				
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
<p><i>525</i> \$800.00</p> <p><i>500</i> \$600.00</p> <p><i>50</i> \$50.00</p> <p><i>50</i> \$50.00</p>				
<p><i>1085</i></p>				
<p><i>Tanpin 97493747</i></p> <p><i>Wp 17/8/21 21540</i></p> <p><i>P/P Resurvey before panel.</i></p> <p><i>2 (3) days</i></p> <p><i>Tanpin C/Mantun.</i></p>				
TOTAL LABOUR				\$1,500.00
ESTIMATE TOTAL				\$4,491.56

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.