

ASS. REC. BY:

Tanglin

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. **MT/1141269-002**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **WP**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SHA3394T** Yr Regn: **2019 / Nov**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Hyundai i30** c.c. **1580**Colour: **Blue** A/C: Insured / Std / NI / NASp. Reading: **-** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **KM HC85/CV 4/88878**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: **195/65 R15**R: **195/65 R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Wuthu**

Front: _____ Rear: _____

R/Bal. **6** mm R/Bal. **6** mmL/Bal. **6** mm L/Bal. **6** mmD.O.A. _____ D.O.I. **17/8/21R1540**Survey held at **Comfort Lodge**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction **Battery weak****COR \$3609.32, 3 days****RED: 882.24; 19%**

Date/Time, File Pass to?

☐ : Prell. Report1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Rep. Format: _____

Lump Sum / L&H ()

Days Of Repair: **3**

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS SI

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA3394T

DATE: 16. August 2021

MAKE HYUNDAI

MVA JUMANI

MODEL IONIQ

DOA: 17. Aug. 2021

NTUC (P/P₁)

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRT BUMPER ASSY			\$430.90
10	FRT BUMPER CLIPS			\$22.00
1	FRT FENDER LH			\$588.80
1	HEADLAMP ASSY LH			\$1,993.65
1	FRT FENDER EMBLEM LH			\$26.60
1	DAY LIGHT LAMP ASSY LH			\$642.50
1	FRT BUMPER BRACKET LH			\$35.00
SUB TOTAL				\$3,739.45
LESS 25% 20%				\$747.89
DISCOUNTED TOTAL				\$2,991.56
				NET
				NET
				\$50.00
				\$800.00
				\$600.00
				\$50.00
				\$50.00
				\$1,500.00
				\$4,491.56
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Labour Charge
PANEL BEATING
SPRAY PAINT
CHECK WIRING
TUFF KOTE

Tanpin 97415747

WP 17/8/21 21540

P/P Resurvey before panel

2-3 days

Tanpin e/Manthun

TOTAL LABOUR

ESTIMATE TOTAL

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order: 4109375

JC NO.: 305483049

OMER
S
OMER NO.
ESS
(R)
(P)
COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

REGN NO.: SHA3394T	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 16.08.2021 16:10
YR OF MANU 14.11.2019	TARGET DATE
CHASSIS CODE KMHC851CVLU188848	COMPLETION DATE/TIME:


UNT CARD NO.

JOB DESCRIPTION

Accident Date: 16.08.2021
NATURE: 3P 16.08.2021

S/NO LABOR CODE

DESCRIPTION



LED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

o.: **SHA3394T** **JU NTUC LKK**

Vehicle No.: **SHA3394T**

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard