

ASSIGNMENT

From: Date:  
Estimated Cost:  
OD / P / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SDE7030T  
at Workshop m/s: Kola workshop  
of  
Insured: GQ 8998X  
Policy No. DMCVSNW00127502000  
Claims No. SNM21D204531/C2/IRENE  
Sum Insured: Excess:  
(Client's Record)  
Make of Veh:

Veh No: SDE7030T Yr Regn: 16/3/21  
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or 4/7  
Make: Honda Civic C.C. 1597  
Colour: Grey A/C: Insured / Std / NI / NA  
Sp. Reading: 12968 T/Radio: Insured / Std / NI / NA  
Eng/No:  
C/No: MRHFC4650LT000479  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 215/55R16  
R:

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.  
Bal. or Market Value: \$96k.  
IDAC Accident Rpt: Consistent? : Yes or No  
GIA / PR Seen: Consistent? : Yes or No  
Est. Repairs: 7 days Res.: Yes or No  
Lum Sum: 151 % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: Person Contacted: LTA 955038  
Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Hankook  
Front 7 mm Rear 7 mm  
R/Bal. 7 mm R/Bal. 7 mm  
L/Bal. mm L/Bal. mm  
D.O.A. 15/8/21 D.O.I. 23/8/21  
Survey held at  
Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
13/10/21 Confirmed P/P @ 8685-44 with posson (Red 3668.83, 29%)

Date/Time, File Pass to?  : Preli. Report  
1)  : Final Report

Days Of Repair: 7  
Resurvey No. of Trip: 1

Date/Time, File Return to?  
2) 13/10/21-typist

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech. Invs (\$ )  
 : Weekend (\$ )

Survey Fee:   
Transportation:   
Photos   
Others   
TOTAL

Report Format : Merimen  
Lump Sum / I.B.I.: (\$ 8685.44 )



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT21002537	<b>Page</b>	1
<b>Registration No</b>	: SDE7030T	<b>Date</b>	: 16. Aug 2021	<b>Customer No.</b>	: WZC008
<b>Chassis No</b>	: MRHFC5650LT000579	<b>Svc Advisor</b>	: YOU PO SOON	<b>Engine No</b>	: R16B25520799
<b>Model</b>	: CIVIC 1.6 VTI YM2020	<b>Date   Time</b>	: 16. Aug 2021 1:31:28 PM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: PURETECH ENGINEERING PTE LTD	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 15/8/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Includ GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: PURETECH ENGINEERING PTE LTD OWNER INSURER: TOKIO MARINE ACC DATE: 15/08/2021 SURVEYED BY: DATE: REF NO: TP INSURER: C/TAIPING TP VEH: GQ8998X						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER <i>DD</i>	1	617.20	25	462.90	32.40	495.30
71510-TEA-T50	GARNISH ASSY,RR.BUMPER LOWER <i>DE</i>	1	128.50	25	96.37	6.75	103.12
71593-TEA-T01	SPACERR,RR.BUMPER SIDE <i>11</i>	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL,RR.BUMPER SIDE <i>11</i>	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER <i>ALL</i>	7	2.30	25	12.07	0.84	12.91
71530-TEA-T00ZZ	BEAM COMP,RR.BUMPER <i>DD</i>	1	188.00	25	141.00	9.87	150.87
66100-TEC-307ZZ	PANEL SETRR. <i>DD</i>	1	277.50	25	208.12	14.57	222.69
66114-TBA-A00ZZ	STIFFENER,R,RR.PANEL SIDE <i>ALL</i>	1	30.50	25	22.87	1.60	24.47
66154-TBA-A00ZZ	STIFFENERL,RR.PANEL SIDE <i>ALL</i>	1	30.50	25	22.87	1.60	24.47
68500-TEA-N00ZZ	LID COMP TRUNK <i>DD</i>	1	554.90	25	416.17	29.13	445.30
74865-TEA-T01	WEATHERSTRIP,TRUNK LID <i>11</i>	1	70.00	25	52.50	3.68	56.18
74890-TEA-T11ZB	GARNISH ASSY,RR.LICENSE <i>A</i>	1	114.80	25	86.10	6.03	92.13
74851-TEA-003	LOCK ASSY,TRUNK <i>11</i>	1	84.90	25	63.67	4.46	68.13
84640-TEA-Z01ZA	LINING ASSY,RR.PANEL <i>11</i>	1	50.30	25	37.72	2.64	40.36
75722-TBA-A00	EMBLEM SETRR. <i>ALL</i>	1	13.40	25	10.05	0.70	10.75
75725-TEA-T01	EMBLEM,RR. <i>ALL</i>	1	12.50	25	9.37	0.66	10.03
75701-TBA-A10	EMBLEM,H-MARK <i>ALL</i>	1	14.00	25	10.50	0.74	11.24
90301-ST0-003	NUT,PUSH 3MM <i>ALL</i>	2	2.10	25	3.15	0.22	3.37
33500-TEA-T01	TAILLIGHT ASSY. <i>11</i>	1	298.40	25	223.80	15.67	239.47

Printed on 16/8/2021 2:04:43 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



# KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b> :	CHINA TAIPING INSURANCE (S'PORE) PTE	<b>Document No.</b> :	SQT21002537	<b>Page</b> :	2
	3 ANSON ROAD #16-00	<b>Date</b> :	16. Aug 2021		
	SPRINGLEAF TOWER	<b>Customer No.</b> :	WZC008		
	SINGAPORE 079909	<b>Svc Advisor</b> :	YOU PO SOON		
<b>Registration No</b> :	SDE7030T	<b>Engine No</b> :	R16B25520799		
<b>Chassis No</b> :	MRHFC5650LT000579	<b>Date   Time</b> :	16. Aug 2021 1:31:28 PM		
<b>Model</b> :	CIVIC 1.6 VTI YM2020	<b>Surveyor Name</b> :			
<b>Owner's Name</b> :	PURETECH ENGINEERING PTE LTD	<b>Survey Date</b> :			
<b>Ins Policy No.</b> :		<b>Authorisation Date</b> :			
<b>Date of Accident</b> :	15/8/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Includ GST
74940-SZW-003	BUZZER ASSYSMART	1	65.40	25	49.05	3.43	52.48
38387-TZ5-A01	ANTENNA ASSYL.F.	1	63.20	25	47.40	3.32	50.72
39530-TEA-H01	CAMERA ASSY,RR VI	1	360.20	25	270.15	18.91	289.06
39680-TEX-Y41ZT	SENSOR ASSY,PARKING	4	155.40	25	466.20	32.63	498.83
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00	X	45.00	3.15	48.15
					<b>Sum Item</b>	<b>2774.27</b>	<b>194.20</b>
							<b>2,968.47</b>
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	20	180.00	12.60	192.60
BOJSE	BODY JOINT SEALANT.	1	100.00	—	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	—	100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	20	250.00	17.50	267.50
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	200.00	30	200.00	14.00	214.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00	35	450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00	35	450.00	31.50	481.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	35	650.00	45.50	695.50
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	450.00	35	450.00	31.50	481.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	3300.00	26	3300.00	231.00	3531.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3400.00	26	3400.00	238.00	3638.00
					<b>Sum Labor</b>	<b>9580.00</b>	<b>670.60</b>
							<b>10,250.60</b>

Survey By

*merous HLL*

Date & Time

*23/8/21 @ 11.00am.*

Excess

Status

*Not Approved*

Signature

*Take 2nd repair painting 7 days*

Total Amount 12,354.27 864.80 13,219.07

Total (Inclusive of GST) 13,219.07

Printed on 16/8/2021 2:04:43 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**HONDA**12/10/2021  
Attn: Marcus

page 1/2

**SERVICE PRE-INVOICE****KAH MOTOR CO. SDN. BHD.** (A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380GCustomer: CU0001298 / CHINA TAIPING  
Chassis No: MRHFC5650LTD00579  
License No: SDE7030T  
Mileage: 12968  
Engine No: R16B25520799Document No: SVO21043165  
Printed By: PSYOU  
Order Date: 21. August 2021  
Order Time: 10:01:03 AM  
Service Advisor: YOU PO SOON

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incld GST
	TP DIRECT SETTLEMENT (J/NO: 76412 ) OWNER: PURETECH ENGINEERING PTE LTD OWNER INSURER: TOKIO MARINE ACC DATE: 15/08/2021 SURVEYED BY: MARCUS CHUA DATE: 23/8/2021 REF NO: TP INSURER: C/TAIPING TP VEH: GQ8998X						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71510-TEA-T50	GARNISH ASSY,RR.BUMPER LOWER	1	128.50	25	96.37	6.75	103.12
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	188.00	25	141.00	9.87	150.87
68100-TEC-307ZZ	PANEL SETRR.	1	277.50	25	208.12	14.57	222.69
66114-TBA-A00ZZ	STIFFENER,R,RR.PANEL SIDE	1	30.50	25	22.87	1.60	24.47
66154-TBA-A00ZZ	STIFFENER,L,RR.PANEL SIDE	1	30.50	25	22.87	1.60	24.47
68500-TEA-N00ZZ	LID COMP TRUNK	1	554.90	25	416.17	29.13	445.30
75722-TBA-A00	EMBLEM SETRR.	1	13.40	25	10.05	0.70	10.75
75725-TEA-T01	EMBLEMRR.	1	12.50	25	9.37	0.66	10.03
75701-TBA-A10	EMBLEM,H-MARK	1	14.00	25	10.50	0.74	11.24
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
	<b>SUM PARTS:</b>				<b>1,415.44</b>	<b>99.88</b>	<b>1,514.52</b>
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BML021	EXT-YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	120.00		120.00	8.40	128.40
BOJSE	0760 BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BOBC	1845 BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	1845 APPLY BODY UNDERSIDE COATING (N).	1	200.00		200.00	14.00	214.00
BA02R	EXT-YJ REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BC011R	0760 REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	350.00		350.00	24.50	374.50
BC012R	0760 RESET VEHICLE SMART ENTRY SYSTEM	1	350.00		350.00	24.50	374.50
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	350.00		350.00	24.50	374.50
BKTRR	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TRUNK LID ADJUST & ALIGN.	1	350.00		350.00	24.50	374.50

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

**SERVICE PRE-INVOICE**GST Ref No.: M200050223  
Company Ref. No.: S60FC1380G

2/2

<b>Customer:</b>	CU0001298 / CHINA TAIPING	<b>Document No:</b>	SVO21043165
<b>Chassis No:</b>	MRHFC5650LT000579	<b>Printed By:</b>	PSYOU
<b>License No:</b>	SDE7030T	<b>Order Date:</b>	21. August 2021
<b>Mileage:</b>	12968	<b>Order Time:</b>	10:01:03 AM
<b>Engine No:</b>	R16B25520799	<b>Service Advisor:</b>	YOU PO SOON

BKRP02M	EXT-YJ CUT OFF & RENEW RR PANEL STRAIGHTEN ALIGN FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	2,600.00	2,600.00	182.00	2,782.00
BP06R	1865 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2,600.00	2,600.00	182.00	2,782.00
			<b>SUM LABOUR:</b>	<b>7,270.00</b>	<b>508.90</b>	<b>7,778.90</b>
			<b>TOTAL SGD</b>	<b>8,685.44</b>	<b>607.98</b>	<b>9,293.42</b>
<b>Total Payable (SGD)</b>						<b>9,293.42</b>

GST Amount is calculated from individual line(s)

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	563R
<b>Vehicle Details</b>	
Vehicle No.:	SDE7030T
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Aug 2021
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Blue
Manufacturing Year:	2021
Engine No.:	R16B25520799
Chassis No.:	MRHFC5650LT000579
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$19,880.00
Original Registration Date:	16 Mar 2021
First Registration Date:	16 Mar 2021
Transfer Count:	0
Actual ARF Paid:	\$19,880.00 ໗໑໔໐
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Mar 2031
PARF Rebate Amount:	\$14,910.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	15 Mar 2031
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,996.00
COE Rebate Amount:	\$40,128.00
<b>Total Rebate Amount:</b>	<b>\$55,038.00</b>

The information contained herein is correct as at 23 Aug 2021

OK