

ASS. REC. BY:

REF:

AIG/21008671/kgf3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ **MASSIVE**

of _____

Insured: _____

Policy No. _____

Claims No. 0709033818SG


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 880k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: Snu 92265 Yr Regn: 08, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____ Wagon

Make: Honda Shuttle c.c. 1498

Colour: n. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 14820 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK8 . 2701933

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / SRim / STD A/Rim or

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 2 mm R/Bal. 2 mm

L/Bal. 2 mm L/Bal. 2 mm

D.O.A. 18/8/21 D.O.I. 19/8/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

2751

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Kenneth confirmed LS \$16900 (Red \$14001.53, 45%)

Date/Time, File Pass to? : Prell. Report : Final Report

1) 12/10 Typist Date/Time, File Return to?

Days Of Repair: 14

Resurvey No. of Trip: 2

Survey Fee:	
Transportation:	
S - RS:	
Others:	
TOTAL	

Add Fee: : Site Insp (\$) : Interview (\$) : Tech Invs (\$) : Weekend (\$)

Report Format: MER-TP Lump Sum ~~16900~~ (\$) 16900

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

Ng Lilin
Blk 876 Woodlands Ave 9
#10-264
Singapore 730876

Not Attached
L.A. 11/11/20

Vehicle No : SMU 9226 S
Make/Model : Honda Shuttle
Year : 2020

Qty	Description	Unit Price	Amount	
<u>Estimate Cost Of Repair</u>				
1 pc	Front bonnet		\$1,305.10	✓
2 pcs	Front bonnet hinge	<i>ds Dis</i> \$95.10	\$190.20	✓
1 pc	Front bonnet lock		\$165.10	✓
1 pc	Front bonnet insulator		\$146.20	X
1 pc	Front wiper garnish		\$195.10	✓
2 pcs	Front fender	<i>o/s Bu</i> \$550.10	\$1,100.20	✓
2 pcs	Front headlamp assy	<i>o/s cm</i> <i>o/s my cm</i> \$2,272.70	\$4,545.40	✓
2 pcs	Front headlamp lower bracket	<i>o/s cm</i> \$155.10	\$310.20	✓
1 pc	Front grille		\$283.70	✓
1 pc	Front grille chrome		\$235.10	✓
1 pc	Front grille emblem		\$55.70	✓
1 pc	Front grille lower chrome moulding		\$165.70	✓
1 pc	Front bumper		\$925.70	✓
1 pc	Front bumper reinforcement		\$385.20	✓
2 pcs	Front bumper side retainer	<i>o/s Dis</i> \$75.10	\$150.20	✓
1 pc	Front bumper lower grille		\$186.70	✓
1 pc	Front bumper tow cover		\$45.60	✓
2 pcs	Front fog lamp chrome garnish		\$194.90	?
2 pcs	Front fog lamp		\$621.10	X
1 pc	Front support panel		\$631.20	✓
1 pc	Front support panel top garnish		\$95.70	?
1 pc	Front o/s chassis		\$405.80	X
2 pcs	Front chassis bracket	<i>o/s R</i> \$187.10	\$375.00	✓
1 pc	Air con condenser		\$887.30	✓
1 pc	Radiator		\$1,483.10	?
1 pc	Radiator fan assy		\$875.10	?
1 pc	Air con fan assy		\$955.10	?
1 pc	Front windscreen washer tank		\$85.70	✓
1 pc	Rear tail-gate assy		\$1,281.10	✓
1 pc	Rear tail-gate glass moulding		\$95.10	✓
1 pc	Rear wiper motor		\$485.10	?
	balance c/f		\$19,678.40	

SMU 9226 S

		balance b/f	\$19,678.40		
1 pc	Rear tail-gate outer garnish	Sm	\$205.10	X	
1 pc	Rear tail-gate emblem "Shuttle "	me	\$45.10	—	
1 pc	Rear tail-gate emblem " H "	me	\$40.10	X	
1 pc	Rear tail-gate outer chrome garnish	Sm	\$385.70	X	
1 pc	Rear tail-gate inner lock	nd	\$305.10	✓	
1 pc	Rear tail-gate inner trim board	nd/mg car	\$387.40	✓	
1 pc	Rear tail-gate pocket handle	Sm	\$45.10	X	
2 pcs	Rear tail-gate reflector		\$485.70	\$971.40	?
2 pcs	Rear tail- lamp	ols?	\$457.10	\$914.20	
2 pcs	Rear tail-lamp panel		\$285.10	\$570.21	X
1 pc	Rear boot rubber	nd/lt		\$195.70	✓
2 pcs	Rear fender inner trim board	mg car	\$485.20	\$970.40	✓
1 pc	Rear end panel	Ry		\$685.10	✓
1 pc	Rear end panel inner garnish	Bu		\$185.90	✓
1 pc	Rear end panel lower cover			\$87.10	?
1 pc	Rear bumper	Ry		\$965.70	✓
1 pc	Rear bumper tow cover	nd		\$48.20	✓
1 pc	Rear bumper center chrome moulding	nd		\$85.60	✓
2 pcs	Rear bumper side retainer	ols dir	\$38.20	\$76.40	✓
2 pcs	Rear bumper reflector		\$155.20	\$310.40	X
2 pcs	Rear bumper reflector garnish	NJP	\$106.70	\$213.40	X
2 pcs	Rear bumper reflector sponge		\$87.10	\$164.20	?
1 pc	Rear tow cover	Repair		\$35.10	X
1 pc	Radio antenna			\$125.60	?
1 pc	Rear spare tyre panel	R		\$1,072.50	?
1 pc	Rear spare tool console box	dir		\$205.60	✓
1 pc	Rear boot top cover board	Bu		\$297.10	✓
1 pc	Rear exhaust silencer	R		\$855.10	X
				\$30,126.91	
		Less 20 %		\$6,025.38	
				\$24,101.53	

S Nett

4 pcs	Rear reverse sensor		\$300.00	?
1 pc	Rear reverse camera	Sm	\$300.00	X
1 pc	Rear tail-gate glass sealant	me	\$55.00	60sm
20 pcs	Rear bumper clip	me	\$40.00	✓
1 pc	Rear no plate	Sm	\$40.00	X
1 pc	Front no plate	nd	\$40.00	✓
1 pc	Front bonnet edge lining	me	\$120.00	60sm
1 pc	Rear tail-gate edge lining	me	\$120.00	60sm
			\$1,015.00	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$2,400.00 1500f

To putty and spray paint

\$2,000.00 1600f

balance c/f \$29,516.53

SMU 9226 S

balance b/f \$29,516.53

Labour Charges

Check & reconnect wiring.	\$45.00	401
To respray anti-rust proofing treatment	\$150.00	1201
Remove/refit rear windscreen to facilitate repair	\$120.00	✓
Remove/refit rear tail-gate mechanism to new door.	\$150.00	601
Remove/refit rear boot upholstery to facilitate repair.	\$100.00	✓
Remove/renew rear exhaust silencer	\$150.00	601
Remove/refit fuel tank to facilitate repair	na	\$150.00 X
Remove/renew air con condenser and to top up gas element	\$180.00	1001
To straighten front chassis alignment	na	\$280.00 X
Check and realign wheel alignment	na	\$60.00 X
Total		<u>\$30,901.53</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 17/08/2021 11:27 (SGT)
Date of Accident 16/08/2021 08:40 (SGT)
Exact Location of Accident KJE, Singapore
Additional Location Information KJE TOWARDS PIE AFTER CCK WEST FLYOVER
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMU9226S

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner NG LILIN (HUANG LILIN)
NRIC No SXXXX511D
Email Address jacngll@yahoo.com
Mobile Phone No (Phone) +65-93899533
Alternative Phone No +65-93899533

VEHICLE PARTICULARS

Manufacturer Honda
Model Shuttle
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1500

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5118655936
Cover Note Number 5118655936

DRIVER

Name of Driver NG LILIN (HUANG LILIN)
NRIC No SXXXX511D

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/trail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Veh A: SMU 9226S
 Veh B: SGM 1635K
 Veh C: SLD 5088D