



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2202049

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 08/04/2022
Reference CC6/CTI21008674/Dpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 4028D
Insured Veh. XE 7368H
Claim No. SNM21D204595/C02
Policy No. DMCVSNW00080202100
Accident Date 17/08/2021
Inspection Date 19/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21008674/Dpa3q2	
			Date: 08/04/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 7368H		Veh. Inspected	SHD 4028D
Policy No.	DMCVSNW00080202100		Coverage (\$)	0.00
Claim No.	SNM21D204595/C02		Excess (\$)	0.00
Assign From			Assign Date	19/08/2021
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ		c.c	1580
Engine No.	HIDDEN		Year of Reg.	2020
Chassis No.	KMHC851CVLU190013		Colour	BLUE
Odometer	107360 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DURATURN	5 mm
	L/H Front Tyre	195/65 R15	DURATURN	5 mm
	R/H Rear Tyre	195/65 R15	DURATURN	5 mm
	L/H Rear Tyre	195/65 R15	DURATURN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/08/2021	Inspection Date	19/08/2021
	Survey held at	Blk 9 Sector C #01-42, Sin Ming Industrial Estate		
	Repairer	BIFROST AUTO PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4028D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	NOT NECESSARY	2,480.40	-
1	BOOT LID 'H' EMBLEM	NOT NECESSARY	28.00	-
1	EMBLEM -HYBRID	NOT NECESSARY	24.30	-
1	EMBLEM -LONIQ	NOT NECESSARY	31.30	-
1	BOOT LID LAMP (RH)	NOT NECESSARY	794.40	-
1	BOOT LID GLASS UPPER MOULDING	NOT NECESSARY	186.30	-
1	BOOT LID GLASS LOWER MOULDING	NOT NECESSARY	145.20	-
1	REAR BUMPER	CUT / MTG BROKEN	459.40	459.40
1	REAR BUMPER CENTRE MOULDING ASSY	NOT NECESSARY	451.25	-
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	NOT NECESSARY	47.50	-
1	REAR BUMPER STAY	NOT NECESSARY	138.10	-
1	REAR BUMPER SIDE RETAINER (RH)	BROKEN	85.80	85.80
1	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SIDE UNDER (RH)	NOT NECESSARY	123.10	-
1	REAR BUMPER REFLECTOR LAMP (RH)	NOT NECESSARY	82.90	-
1	TAIL LAMP (RH)	CRACKED / CUT	870.40	870.40
1	TAIL LAMP QUARTER PANEL (RH)	NOT NECESSARY	208.90	-
1	REAR PANEL	NOT NECESSARY	532.00	-
1	REAR PANEL GARNISH	NOT NECESSARY	346.80	-
1	EXHAUST SILENCER	NOT NECESSARY	943.50	-
1	REAR FENDER (RH)	DENTED	1,768.30	1,768.30
1	REAR FENDER SHIELD REAR PIECE (RH)	TORN	173.60	173.60
1	REAR FENDER SHIELD FRT PIECE (RH)	DEFORMED	165.50	165.50
1	REAR FENDER AIR-DUCT (RH)	BROKEN	87.30	87.30
1	ASSY BSD BLIND SPOT RADAR (RH)	MTG BENT	1,625.00	1,625.00
1	WIRING HARNESS BWS EXT	NOT NECESSARY	988.90	-
1	REAR TYRE RIM (RH)	DISTORTED	1,124.20	1,124.20
1	REAR WHEEL HUP-CAP (RH)	CUT	346.40	346.40
1	REAR WHEELBEARING & HUB ASSY	NOT NECESSARY	554.00	-
1	REAR TRAILING ARM (RH)	NOT NECESSARY	265.40	-

Report Ref No. CC6/CTI21008674/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR ASSIST (RH)	NOT NECESSARY	227.90	-
1	REAR SHOCK ABSORBER (RH)	NOT NECESSARY	230.50	-
1	REAR SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	133.10	-
1	REAR ABSORBER STOPPER (RH)	NOT NECESSARY	137.60	-
1	REAR ABSORBER COVER (RH)	NOT NECESSARY	175.60	-
1	REAR CROSSMEMBER	NOT NECESSARY	1,468.70	-
1	STABILIZER BAR	NOT NECESSARY	387.30	-
1	STABILIZER LINK (RH)	NOT NECESSARY	147.30	-
1	REAR UPPER ARM (RH)	NOT NECESSARY	239.50	-
1	REAR LOWER ARM (RH)	NOT NECESSARY	393.10	-
1	REAR KNUCKLE ARM (RH)	NOT NECESSARY	538.10	-
	LESS 20% DISCOUNT		-3,835.77	-1,345.58
			15,343.08	5,382.32
	<u>SPECIAL NETT ITEMS</u>			
1	BOOT LID COMFORT LOGO & TEL NO.STICKER (SN)	NOT NECESSARY	35.00	-
1	BOOT LID COMFORT CABLINK TEL NO STICKER (SN)	NOT NECESSARY	30.00	-
2	REAR WINDSCREEN SEALANT @\$46.00 (SN)	NOT NECESSARY	92.00	-
1	REAR TYRE (RH) (SN)	NOT NECESSARY	216.00	-
			373.00	-
	<u>LABOUR</u>			
	PANEL BEATING.		1,600.00	600.00
	SPRAY PAINTING CHARGE.		1,200.00	400.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		100.00	20.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE /REFIX CUSHION & UPHOLSTERY REAR .		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS .	NOT NECESSARY	240.00	-
	REMOVE/REFIX REVERSE SENSOR .	NOT NECESSARY	120.00	-
	REMOVE/REFIX UNDERCARRIAGE (RR).	NOT NECESSARY	400.00	-
	RE-SET REAR ABS SYSTEM.	NOT NECESSARY	400.00	-
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	80.00	-
	REMOVE/REFIX EXHAUST PIPE.	NOT NECESSARY	80.00	-

Report Ref No. CC6/CTI21008674/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.}		550.00	150.00
	DIAGNOSTIC & RESETTING ADAS OPTICAL SENSOR.}		550.00	-
			5,770.00	1,340.00
GRAND TOTAL			21,486.08	6,722.32
RECOMMENDED COST OF REPAIRS				6,722.32

Report Ref No. CC6/CTI21008674/Dpa3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4028D

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4028D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4028D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

