

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 18-Aug-21

INSURANCE: China Teping.

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHD4028D

Description	Qty	List Price	Amount
Boot Lid <i>HH</i>	1	\$ 2,480.40	\$ 2,480.40
Boot Lid 'H' Emblem <i>HH</i>	1	\$ 28.00	\$ 28.00
Emblem-Hybrid <i>HH</i>	1	\$ 24.30	\$ 24.30
Emblem-Ioniq <i>HH</i>	1	\$ 31.30	\$ 31.30
Boot Lid Lamp(RH) <i>HH</i>	1	\$ 794.40	\$ 794.40
Boot Lid Glass Upper Moulding <i>HH</i>	1	\$ 186.30	\$ 186.30
Boot Lid Glass Lower Moulding <i>HH</i>	1	\$ 145.20	\$ 145.20
Rear Bumper <i>Cut / mainly broken</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Centre Moulding Assy <i>HH</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>HH</i>	1	\$ 47.50	\$ 47.50
Rear Bumper Stay <i>HH</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Side retainer (RH) <i>broken</i>	1	\$ 85.80	\$ 85.80
Rear Bumper Cover Clips <i>HH</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Side Under(RH) <i>HH</i>	1	\$ 123.10	\$ 123.10
Rear Bumper Reflector Lamp(RH) <i>HH</i>	1	\$ 82.90	\$ 82.90
Tail Lamp(RH) <i>check / cut</i>	1	\$ 870.40	\$ 870.40
Tail Lamp Quarter Panel(RH) <i>HH</i>	1	\$ 208.90	\$ 208.90
Rear Panel <i>HH</i>	1	\$ 532.00	\$ 532.00
Rear Panel Garnish <i>HH</i>	1	\$ 346.80	\$ 346.80
Exhaust Silencer <i>HH</i>	1	\$ 943.50	\$ 943.50
Rear Fender(RH) <i>Deformed</i>	1	\$ 1,768.30	\$ 1,768.30
Rear Fender SHIELD REAR PIECE (RH) <i>for torn</i>	1	\$ 173.60	\$ 173.60
Rear Fender SHIELD Frt Piece (RH) <i>deformed</i>	1	\$ 165.50	\$ 165.50
Rear Fender Air-Duct (RH) <i>broken</i>	1	\$ 87.30	\$ 87.30
Assy BSD Blind Spot Radar (RH) <i>mainly broken</i>	1	\$ 1,625.00	\$ 1,625.00
Wiring Harness BWS Ext <i>HH</i>	1	\$ 988.90	\$ 988.90
Rear Tyre Rim (RH) <i>distorted</i>	1	\$ 1,124.20	\$ 1,124.20
Rear Wheel Hub-Cap (RH) <i>cut</i>	1	\$ 346.40	\$ 346.40
Rear Wheelbearing & Hub assy <i>HH</i>	1	\$ 554.00	\$ 554.00
Rear Trailing Arm(RH) <i>HH</i>	1	\$ 265.40	\$ 265.40
Rear Assist (RH) <i>HH</i>	1	\$ 227.90	\$ 227.90
Rear shock Absorber(RH) <i>HH</i>	1	\$ 230.50	\$ 230.50
Rear Shock Absorber Mounting (RH) <i>HH</i>	1	\$ 133.10	\$ 133.10
Rear Absorber stopper (RH) <i>HH</i>	1	\$ 137.60	\$ 137.60
Rear Absorber Cover (RH) <i>HH</i>	1	\$ 175.60	\$ 175.60
Rear Crossmember <i>HH</i>	1	\$ 1,468.70	\$ 1,468.70
Stabilizer Bar <i>HH</i>	1	\$ 387.30	\$ 387.30
Stabilizer Link (RH) <i>HH</i>	1	\$ 147.30	\$ 147.30
Rear Upper Arm(RH) <i>HH</i>	1	\$ 239.50	\$ 239.50
Rear Lower Arm(RH) <i>HH</i>	1	\$ 393.10	\$ 393.10
Rear Knuckle Arm (RH) <i>HH</i>	1	\$ 538.10	\$ 538.10
SUB TOTAL			\$ 19,178.85

LESS 20%					\$ 3,835.77
DISCOUNTED TOTAL					\$ 15,343.08
Boot Lid Comfort Logo & Tel No. Sticker <i>HH</i>	SN	1	\$	35.00	\$ 35.00
Boot Lid Comfort Cablink Tel No. Sticker <i>HH</i>	SN	1	\$	30.00	\$ 30.00
Rear Windscreen Sealant <i>HH</i>	SN	2	\$	46.00	\$ 92.00
Rear Tyre(RH) <i>HH</i>	SN	1	\$	216.00	\$ 216.00
SUB TOTAL					\$ 373.00
Labour Charge					
Panel Beating		1	\$	1,600.00	\$1,600.00
Spray Painting Charge		1	\$	1,200.00	\$1,200.00
Wiring Charge		1	\$	100.00	\$100.00
Tuff Kote		1	\$	100.00	\$100.00
Towing Charge		1	\$	80.00	\$80.00
Remove/Refix Cushion & Upholstery Rear		1	\$	150.00	\$150.00
Remove/Refix Rear Windscreen Glass		2	\$	120.00	\$240.00
Remove/Refix Reverse Sensor		1	\$	120.00	\$120.00
Remove/Refix Undercarriage (RR)		1	\$	400.00	\$400.00
Re-set Rear ABS System		1	\$	400.00	\$400.00
Remove/Refix Fuel Tank		1	\$	80.00	\$80.00
Remove/Refix Exhaust Pipe		1	\$	80.00	\$80.00
Four Wheel Alignment		1	\$	120.00	\$120.00
Diagnostic & Resetting To Erase Fault Code		1	\$	550.00	\$550.00
Diagnostic & Resetting ADAS Optical sensor		1	\$	550.00	\$550.00
TOTAL LABOUR					\$5,770.00
ESTIMATE TOTAL					\$ 21,486.08
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance					

6727-90

5382.32

600/-

400/-

30/-

20/-

HH

80/-

HH

HH

HH

HH

HH

HH

60/-

HH

150/-

1340.00

19/08/2021 @ 1730hrs

NA Andrew

Part by Part 56

Photo after repair 4 days.

with damage part.

Ryan

LKK Auto

P/P 6,722.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: