

**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Estimate

Vehicle No:  
Make and model:

SMK7251J  
Mitsubishi Outlander

2019

Qty Spare parts

List price

- 1 Tailgate
- 1 Tailgate windscreen glass rubber moulding
- 1 Tailgate "Outlander" emblem
- 1 Tailgate "Mivec" emblem
- 1 Tailgate chrome garnish
- 1 Tailgate chromne garnish centre emblem
- 1 Tailgate number plate lamp
- 1 Tailgate number plate lamp
- 1 Tailgate open button sensor
- 1 Tailgate RH lamp assy
- 1 Tailgate LH lamp assy
- 1 Tailgate inner trim board
- 1 Tailgate lock
- 1 Tailgate lock catch
- 1 Tailgate weatherstrip
- 1 Tailgate wiper motor
- 1 Tailgate wiper motor bracket
- 1 Tailgate wiper arm
- 1 Tailgate RH side lock sensor
- 1 Tailgate LH side lock sensor
- 1 Tailgate RH damper
- 1 Tailgate LH damper
- 1 Tailgate pull handle
- 1 Rear bumper
- 1 Rear bumper pad (black)
- 1 Rear bumper lower (silver)
- 1 Rear bumper RH reflector assy
- 1 Rear bumper LH reflector assy
- 1 Rear bumper RH side retainer
- 1 Rear bumper LH side retainer
- 1 Rear bumper RH side garnish
- 1 Rear bumper LH side garnish
- 1 Rear bumper reinforcement RH bracket
- 1 Rear bumper reinforcement LH bracket
- 1 Rear bumper centre bracket
- 1 RH taillamp assy
- 1 LH taillamp assy

|    |                   |          |        |
|----|-------------------|----------|--------|
| \$ | 989.00            | 1,089.00 | DD ✓   |
| \$ |                   | ✓ 86.00  | NECV ✓ |
| \$ |                   | ✓ 95.00  | NECV ✓ |
| \$ |                   | ✓ 42.00  | NECV ✓ |
| \$ | X                 | 496.00   | X NN   |
| \$ | X                 | 57.00    | X NN   |
| \$ |                   | 37.80    | NDX    |
| \$ |                   | 37.80    | NDX    |
| \$ |                   | 301.00   | NDX    |
| \$ | <del>238.00</del> | 506.00   | X NN   |
| \$ | <del>238.00</del> | 506.00   | X NN   |
| \$ | <del>312.00</del> | 364.00   | X NN   |
| \$ | 450.00            | 477.00   | JMV ✓  |
| \$ |                   | 23.00    | NDX    |
| \$ |                   | 213.00   | NDX    |
| \$ |                   | 437.00   |        |
| \$ |                   | 29.00    | NDX    |
| \$ |                   | 67.00    |        |
| \$ |                   | 428.00   | ? NSX  |
| \$ |                   | 428.00   |        |
| \$ |                   | 198.00   | NDX    |
| \$ |                   | 198.00   |        |
| \$ |                   | 32.00    | NDX    |
| \$ |                   | ✓ 811.00 | BRV ✓  |
| \$ |                   | ✓ 292.00 | BRV ✓  |
| \$ |                   | ✓ 384.00 | BRV ✓  |
| \$ |                   | X 103.00 | X NN   |
| \$ |                   | 103.00   | NDX    |
| \$ | 18.00             | ✓ 18.00  | NECV ✓ |
| \$ | 18.00             | ✓ 18.00  |        |
| \$ |                   | 106.00   | NDX    |
| \$ |                   | 106.00   |        |
| \$ |                   | ✓ 64.00  | ? BTV  |
| \$ |                   | ✓ 64.00  |        |
| \$ |                   | 43.00    | NSX    |
| \$ |                   | ✓ 615.00 | ? BRV  |
| \$ |                   | ✓ 615.00 |        |

- 1 End panel
- 1 End panel inner garnish
- 1 keyless sensor
- 1 Buzzer sensor
- 1 Rear LH fender inner trim board
- 1 Rear RH fender inner trim board
- 1 Rear compartment panel cargo box
- 1 Rear compartment panel cargo box cover
- 1 Spare tyre carriage
- 1 Exhaust silencer
- 1 Exhaust silencer gasket

|    |                   |       |
|----|-------------------|-------|
| \$ | ✓ 255.00          | 3DY   |
| \$ | ✓ 115.00          | BR ✓  |
| \$ | <del>96.00</del>  | ? NDX |
| \$ | ✓ 91.00           | -BR ✓ |
| \$ | ✓ 633.00          | BR ✓  |
| \$ | ✓ 633.00          | BR ✓  |
| \$ | <del>101.00</del> |       |
| \$ | <del>255.00</del> |       |
| \$ | <del>250.00</del> |       |
| \$ | <del>538.50</del> | NDX   |
| \$ | <del>42.10</del>  |       |

|         |         |           |
|---------|---------|-----------|
| \$      | 7714.40 | 12,487.20 |
| -10% \$ | 771.44  | 1,248.72  |
| \$      |         | 11,238.48 |
|         | 6942.96 |           |

#### Qty Spare parts

- 1 Tailgate "C&C" emblem
- 1 Tailgate windscreen glass sealant
- 1 Tailgate windscreen glass inner seal
- 1set Tailgate inner trim board clips
- 1 Tailgate reverse camera
- 1 Rear bumper clips
- 1set Rear bumper reverse sensor
- 1set Rear RH fender inner trim board clips
- 1set Rear LH fender inner trim board clips
- 1 End panel joint sealant

| <u>Special Nett price</u> |                  |                        |
|---------------------------|------------------|------------------------|
| \$                        | ✓ 75.00          | NECV ✓                 |
| \$                        | 30.00            | 70.00 NECV ✓           |
| \$                        | 30.00            | 50.00 NECV ✓           |
| \$                        | <del>30.00</del> | 70.00 XECN ✓           |
| \$                        |                  | <del>650.00</del> NDX  |
| \$                        | 30.00            | 70.00 NECV ✓           |
| \$                        | 200.00           | <del>280.00</del> SC ✓ |
| \$                        | 20.00            | 70.00 } NEC ✓          |
| \$                        | 20.00            | 70.00 } ✓              |
| \$                        | 30.00            | 70.00 ? NECV ✓         |
|                           | 465.00           |                        |

#### Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.  
To panel beating, cut / weld and re-align all affected panels

|    |        |            |
|----|--------|------------|
| \$ | 600.00 | 1,000.00 ✓ |
|----|--------|------------|

Spray painting on affected panels

|    |        |            |
|----|--------|------------|
| \$ | 600.00 | 1,000.00 ✓ |
|----|--------|------------|

Check wiring and lighting system

|    |  |           |
|----|--|-----------|
| \$ |  | 70.00 NNX |
|----|--|-----------|

Apply rust coating chemical on affected panels

|    |  |           |
|----|--|-----------|
| \$ |  | 80.00 NNX |
|----|--|-----------|

Remove, replace and reinstall tailgate windscreen glass and sealants to assist repair

|    |        |          |
|----|--------|----------|
| \$ | 120.00 | 200.00 ✓ |
|----|--------|----------|

Remove and replace tailgate inner mechanism to new tailgate

|    |       |          |
|----|-------|----------|
| \$ | 60.00 | 100.00 ✓ |
|----|-------|----------|

Remove, replace and adjust tailgate reverse camera to assist repair

|    |  |            |
|----|--|------------|
| \$ |  | 100.00 NNX |
|----|--|------------|

Remove and replace rear inner trims, garnish and boards to assist repair

\$ 150.00

~~280.00~~ ✓

Remove and replace rear bumper reverse sensor to assist repair

\$ 60.00

~~70.00~~ ✓

Remove and replace exhaust silencer and gasket to assist repair

\$

~~150.00~~ N/A

1590.00

Survey

Resurvey

19/8/2021

20/8/2021

140 hrs

1553 hrs

TGrim Min

TGrim Min

Lump sum repair

Repair days 7

Total: \$

15,763.48

Panels

5613.00

S N

465.00

Labour

1590.00

7668.00

LS 6100/2

TGrim Min  
21/9/2021

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: