

ASS. REC. BY:

REF: CS/

AIG / 210086781Kw3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLZ 1651K

at Workshop m/s: Tong Luck

of _____

Insured: _____

Policy No. 0999993598

Claims No. 6686224615SG

Sum Insured: _____ Excess: \$1700

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \$160k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLZ 1651K Yr Regn: 04 18

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mercedes c.c. 1991

Colour: M. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 87773 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2130452A 414492

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 245/43R18

R: 275/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 1/8/21 D.O.I. 19/8/2021

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

20/8/2021 Revert to AIG via Merimen.

20/8/2021 Insurance informed C/A via Merimen.

23/8/2021 Informed Candy C/A & ex: \$1700 via email.

Confirmed P/P 29861.19, 10 repair days (RED \$4102.06; 12%)

Date/Time, File Pass to? : Prel. Report

11/18/11 TYPIST : Final Report

Date/Time, File Return to? _____

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

S - RS - SI _____

Fees _____

Others _____

TOTAL _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Report Format: MER-OD

Lump Sum / I.B.I: (\$ 29861.19)



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

*Not Authorized
Assembly B4 paint*

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

10 days

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/08/2021

ESTIMATE

NO : QUOT202108-000029(00)

DATE : 18/08/2021

POLICY NO : 999995580

VEH REG NO : SLZ1651K

MAKE/MODEL : MERCEDES BENZ E250 AVG
(R18 LED)

CHASSIS NO : WDD2130452A414492

ENGINE NO : 27492031389300

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SLZ1651K

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Front windscreen glass	1	850.00	850.00
2 Roof lining	1	1,120.00	1,120.00
3 Window air bag - RH / LH	2	850.00	1,700.00
4 Dashboard assy	1	2,480.00	2,480.00
5 Steering air bag	1	1,880.00	1,880.00
6 Passenger air bag	1	1,280.00	1,280.00
7 Knee air bag	1	850.00	850.00
8 Airbag control unit	1	680.00	680.00
9 Airbag sensor	1	155.00	155.00
10 Front safety belt - RH / LH	2	950.00	1,900.00
11 Rear safety belt - RH / LH	2	420.00	840.00
12 Bonnet	1	1,350.00	1,350.00
13 Bonnet centre logo	1	68.00	68.00
14 Bonnet insulator	1	198.00	198.00
15 Bonnet insulator clips	10	6.50	65.00
16 Bonnet hinge - RH / LH	2	135.00	270.00
17 Bonnet spring - LH	1	28.00	28.00
18 Bonnet lock - LH	1	62.00	62.00
19 Bonnet lock switch - LH	1	45.00	45.00
20 Support panel	1	650.00	650.00
21 Support panel top garnish clips	6	5.00	30.00
22 Headlamp assy - RH / LH	2	1,980.00	3,960.00
23 Headlamp bracket - LH	1	65.00	65.00
24 Front grille	1	165.00	165.00
25 Front grille outer chrome	1	190.00	190.00
26 Front grille beam	1	225.00	225.00
27 Front grille beam moulding	2	58.00	116.00
28 Front grille support	1	178.00	178.00
29 Front grille inner garnish	1	95.00	95.00
30 Front bumper	1	850.00	850.00
31 Front bumper reinforcement	1	395.00	395.00
32 Front bumper bracket - LH	1	168.00	168.00
33 Front bumper inner carrier - LH	1	75.00	75.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 01/08/2021

ESTIMATE

NO : QUOT202108-000029(00)
DATE : 18/08/2021
POLICY NO : 999995580
VEH REG NO : SLZ1651K
MAKE/MODEL : MERCEDES BENZ E250 AVG
(R18 LED)
CHASSIS NO : WDD2130452A414492
ENGINE NO : 27492031389300
REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SLZ1651K

Description	Quantity	Unit Price	Amount
		S\$	S\$
34 Front bumper strut - LH	1	42.00	42.00 ?
35 Front bumper sponge	1	152.00	152.00 ✓
36 Front bumper centre grille	1	96.00	96.00 ✓
37 Front bumper lower inner frame	1	105.00	105.00 ?
38 Front bumper side retainer - LH	1	24.00	24.00 ✓
39 Front bumper sensor	1	138.00	138.00 ✓
40 Front bumper sensor seal	6	8.00	48.00 ✓
41 Front bumper sensor cable	1	130.00	130.00 ?
42 Front bumper clips	15	5.50	82.50 ✓
43 Front bumper lower chrome	1	118.00	118.00 ✓
44 Front bumper lower lid	1	115.00	115.00 ✓
45 Front bumper under cover	1	168.00	168.00 ✓
46 Front number plate garnish	1	98.00	98.00 ?
47 Front fender - LH	1	628.00	628.00 X
48 Front fender inner shield clips - LH	20	6.50	130.00 X
49 Front sport rim - LH	1	750.00	750.00 ✓
			25,923.50
		Add 10%	2,464.75
			28,388.25
SPECIAL NET			
50 ERP bracket	1	35.00	35.00 265m
51 Front windscreen sealant	1	60.00	60.00 405m
52 Front number plate	1	40.00	40.00 ✓
			135.00
LABOUR			
53 To remove and refit air-con condenser and refill air-con gas	1	150.00	150.00 100l
54 To remove and refit dashboard, meter and grove box compartment to facilitates the repair	1	580.00	580.00 300l
55 To remove and refit front windscreen glass	1	150.00	150.00 120l
56 To dismantle and refit console box to enable replace airbag control unit	1	280.00	280.00 180l
57 To remove and replace roofing lining	1	120.00	120.00 80l
58 To remove and replace steering airbag, passenger airbag, knee airbag, front and rear safety belt, airbag control unit and airbag sensor	1	800.00	800.00 400l
59 To check and rectify wiring system	1	80.00	80.00 20l



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722
Tel: 6250 0088 Fax: 6250 5545
Email: operation@tlauto.com.sg
GST No: 201700521W UEN No: 201700521W

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000
FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 01/08/2021

ESTIMATE

NO : QUOT202108-000029(00)
DATE : 18/08/2021
POLICY NO : 999995580
VEH REG NO : SLZ1651K
MAKE/MODEL : MERCEDES BENZ E250 AVG (R18 LED)
CHASSIS NO : WDD2130452A414492
ENGINE NO : 27492031389300
REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SLZ1651K

Description	Quantity	Unit Price	Amount
60 To panel beat and straighten LH front fender inner panel, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,500.00	1,500.00
61 To putty and spray paint on affected areas	1	1,200.00	1,200.00
62 To re-program and reset all control module faulty code	1	580.00	580.00
			5,440.00
		TOTAL	S\$ 33,963.25
		ADD GST @ 7%	2,377.43
		GRAND TOTAL	S\$ 36,340.68

600
600
7

SINGAPORE DOLLAR THIRTY-SIX THOUSAND THREE HUNDRED FORTY AND CENTS SIXTY-EIGHT ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 778Z

Vehicle Details

Vehicle No.: SLZ1651K

Vehicle to be Exported: No

Intended Deregistration Date: 15 Aug 2021

Vehicle Make: MERCEDES BENZ

Vehicle Model: E250 AVG (R18 LED)

Primary Colour: Grey

Manufacturing Year: 2018

Engine No.: 27492031389300

Chassis No.: WDD2130452A414492

Maximum Power Output: 155.0 kW (207 bhp)

Open Market Value: \$58,503.00

Original Registration Date: 25 Apr 2018

First Registration Date: 25 Apr 2018

Transfer Count: 0

Actual ARF Paid: \$77,306.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 24 Apr 2028

PARF Rebate Amount: \$57,979.00

Intended COE Rebate Details

COE Expiry Date: 24 Apr 2028

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$37,010.00

COE Rebate Amount: \$24,765.00

Total Rebate Amount: \$82,744.00

The information contained herein is correct as at 03 Aug 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforsaid.

ACCIDENT STATEMENT

Date of Submission	02/08/2021 22:48 (SGT)
Date of Accident	01/08/2021 18:40 (SGT)
Exact Location of Accident	660 Jurong West Street 64, Singapore 640660
Additional Location Information	Entrance of MSCP ramp going to level 1b
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ1651K
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD
Company Reg No	1XXXXX778Z
Email Address	eugene.koh@daimler.com
Mobile Phone No	(Phone) +65-91876216
Alternative Phone No	(Office) +65-68498118

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E250
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2143

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999995580
Cover Note Number	-

DRIVER

Name of Driver	ZHENG HONGBO
NRIC No	SXXXX430H

Going up to
MSCP Level 1B

