



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

*Not authorized
Return B4 pain*

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/08/2021

*19/8/21 10 days
24/9/21*

ESTIMATE

NO : QUOT202108-000029(00)

DATE : 18/08/2021

POLICY NO : 999995580

VEH REG NO : SLZ1651K

MAKE/MODEL : MERCEDES BENZ E250 AVG
(R18 LED)

CHASSIS NO : WDD2130452A414492

ENGINE NO : 27492031389300

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SLZ1651K

Description	Quantity	Unit Price	Amount	
			S\$	S\$
PARTS				
1 Front windscreen glass	1	850.00	CM	850.00 ✓
2 Roof lining	1	1,120.00		1,120.00 ✓
3 Window air bag - RH / LH	2	850.00	Return	1,700.00 ✓
4 Dashboard assy	1	2,480.00	Return	2,480.00 ✓
5 Steering air bag	1	1,880.00	Return	1,880.00 ✓
6 Passenger air bag	1	1,280.00	Return	1,280.00 ✓
7 Knee air bag	1	850.00	Return	850.00 ✓
8 Airbag control unit	1	680.00	Return	680.00 ✓
9 Airbag sensor	1	155.00	Return	155.00 ✓
10 Front safety belt - RH / LH	2	950.00	Return	1,900.00 ✓
11 Rear safety belt - RH / LH	2	420.00	Return	840.00 ✓
12 Bonnet	1	1,350.00	Return	1,350.00 ✓
13 Bonnet centre logo	1	68.00	Return	68.00 ✓
14 Bonnet insulator	1	198.00		198.00 ✓
15 Bonnet insulator clips <i>necessary</i>	10	6.50	40SN	65.00 ✓
16 Bonnet hinge - RH / LH	2	135.00		270.00 ✓
17 Bonnet spring - LH	1	28.00		28.00 ✓
18 Bonnet lock - LH	1	62.00		62.00 ✓
19 Bonnet lock switch - LH	1	45.00		45.00 ✓
20 Support panel	1	650.00	Return	650.00 ✓
21 Support panel top garnish clips	6	5.00	20SN	30.00 ✓
22 Headlamp assy - RH / LH	2	1,980.00	my car	3,960.00 ✓
23 Headlamp bracket - LH ✓	1	65.00	car	65.00 ✓
24 Front grille	1	165.00	car	165.00 ✓
25 Front grille outer chrome	1	190.00	car	190.00 ✓
26 Front grille beam	1	225.00	car	225.00 ✓
27 Front grille beam moulding	2	58.00	CM	116.00 ✓
28 Front grille support	1	178.00	CM	178.00 ✓
29 Front grille inner garnish ✓	1	95.00	car	95.00 ✓
30 Front bumper	1	850.00	car	850.00 ✓
31 Front bumper reinforcement	1	395.00	Return	395.00 ✓
32 Front bumper bracket - LH	1	168.00		168.00 ✓
33 Front bumper inner carrier - LH ✓	1	75.00	car	75.00 ✓

22/117



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/08/2021

ESTIMATE

NO : QUOT202108-000029(00)

DATE : 18/08/2021

POLICY NO : 999995580

VEH REG NO : SLZ1651K

MAKE/MODEL : MERCEDES BENZ E250 AVG
(R18 LED)

CHASSIS NO : WDD2130452A414492

ENGINE NO : 27492031389300


REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SLZ1651K

Description	Quantity	Unit Price	Amount	
			S\$	S\$
34 Front bumper strut - LH ✓	1	42.00	bt ✓	42.00 ✓
35 Front bumper sponge	1	152.00	CM ✓	152.00 ✓
36 Front bumper centre grille	1	96.00	nu ✓	96.00 ✓
37 Front bumper lower inner frame ✓	1	105.00	cuq ✓	105.00 ✓
38 Front bumper side retainer - LH	1	24.00	Di's ✓	24.00 ✓
39 Front bumper sensor	1	138.00	nu ✓	138.00 ✓
40 Front bumper sensor seal	6	8.00	nu ✓	48.00 ✓
41 Front bumper sensor cable	1	130.00		130.00 an
42 Front bumper clips	15	5.50	nu ✓	82.50 ✓
43 Front bumper lower chrome	1	118.00	CRA ✓	118.00 ✓
44 Front bumper lower lid	1	115.00	CM ✓	115.00 ✓
45 Front bumper under cover - Centre.	1	168.00	CRA ✓	168.00 ✓
46 Front number plate garnish	1	98.00		98.00 an
47 Front fender - LH	1	628.00	R ✓	628.00 XR
48 Front fender inner shield clips - LH	20	6.50	nu ✓	130.00 an
49 Front sport rim - LH ✓	1	750.00	nu ✓	750.00 ✓
				25,923.50
			Add 10%	2,464.75
				28,388.25
SPECIAL NET				
50 ERP bracket	1	35.00	nu ✓	35.00 ✓
51 Front windscreen sealant	1	60.00	nu ✓	60.00 ✓
52 Front number plate	1	40.00	mi's ✓	40.00 ✓
				135.00
LABOUR				
53 To remove and refit air-con condenser and refill air-con gas	1	150.00		150.00 X
54 To remove and refit dashboard, meter and grove box compartment to facilitates the repair	1	580.00		580.00 300
55 To remove and refit front windscreen glass	1	150.00		150.00 120
56 To dismantle and refit console box to enable replace airbag control unit	1	280.00		280.00 180
57 To remove and replace roofing lining	1	120.00		120.00 80
58 To remove and replace steering aigbag, passenger airbag, knee airbag. front and rear safety belt, airbag control unit and airbag sensor	1	800.00		800.00 400
59 To check and rectify wiring system	1	80.00		80.00 20

Handwritten notes:
 R 23,873.00
 10% 2,387.30
 R 26,260.30

Handwritten notes:
 1756
 265m
 405
 216



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 3

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 01/08/2021

ESTIMATE

NO : QUOT202108-000029(00)
DATE : 18/08/2021
POLICY NO : 999995580
VEH REG NO : SLZ1651K
MAKE/MODEL : MERCEDES BENZ E250 AVG
(R18 LED)
CHASSIS NO : WDD2130452A414492
ENGINE NO : 27492031389300
REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SLZ1651K

Description	Quantity	Unit Price	Amount
		S\$	S\$
60 To panel beat and straighten LH front fender inner panel, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,500.00	1,500.00
61 To putty and spray paint on affected areas	1	1,200.00	1,200.00
62 To re-program and reset all control module faulty code	1	580.00	580.00
			5,440.00
		TOTAL	S\$ 33,963.25
		ADD GST @ 7%	2,377.43
		GRAND TOTAL	S\$ 36,340.68

6001
6001
480
7
2880

SINGAPORE DOLLAR THIRTY-SIX THOUSAND THREE HUNDRED FORTY AND CENTS SIXTY-EIGHT ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/08/2021

ESTIMATE

NO : QUOT202108-000029(00)

DATE : 24/09/2021

POLICY NO : 999995580

VEH REG NO : SLZ1651K

MAKE/MODEL : MERCEDES BENZ E250 AVG
(R18 LED)

CHASSIS NO : WDD2130452A414492

ENGINE NO : 27492031389300

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SLZ1651K

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Knee airbag under cover	1	250.90	250.90
2 Front bumper under cover - LH	1	88.00	88.00
3 Front bumper pressure sensor	1	155.00	155.00
4 Horn bracket - RH / LH	2	28.00	56.00
			549.90
		Add 10%	54.99
			604.89
TOTAL			S\$ 604.89
ADD GST @ 7%			42.34
GRAND TOTAL			S\$ 647.23

SINGAPORE DOLLAR SIX HUNDRED FORTY-SEVEN AND CENTS TWENTY-THREE ONLY

parts : \$ 26,260.30
 SN : 216.00
 Labour : 2,880.00
 Supp : 604.89

\$ 29,961.19

XS 1,700.00

\$ 28,261.19

7% 1,978.28

\$ 30,239.47

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE