



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

Not Authorized
Primary B4 paint

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/08/2021

19/8/21 10 days

ESTIMATE

NO : QUOT202108-000029(00)

DATE : 18/08/2021

POLICY NO : 999995580

VEH REG NO : SLZ1651K

MAKE/MODEL : MERCEDES BENZ E250 AVG
(R18 LED)

CHASSIS NO : WDD2130452A414492

ENGINE NO : 27492031389300

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SLZ1651K

Description	Quantity	Unit Price		Amount	
		S\$	S\$	S\$	S\$
PARTS					
1 Front windscreen glass	1	850.00	CM	850.00	✓
2 Roof lining	1	1,120.00		1,120.00	✓
3 Window air bag - RH / LH	2	850.00	Return	1,700.00	✓
4 Dashboard assy	1	2,480.00	Return	2,480.00	✓
5 Steering air bag	1	1,880.00	Return	1,880.00	✓
6 Passenger air bag	1	1,280.00	Return	1,280.00	✓
7 Knee air bag	1	850.00	Return	850.00	✓
8 Airbag control unit	1	680.00	Return	680.00	✓
9 Airbag sensor	1	155.00	Return	155.00	✓
10 Front safety belt - RH / LH	2	950.00	Return	1,900.00	✓
11 Rear safety belt - RH / LH	2	420.00	Return	840.00	✓
12 Bonnet	1	1,350.00	Return	1,350.00	✓
13 Bonnet centre logo	1	68.00	Return	68.00	✓
14 Bonnet insulator	1	198.00	Return	198.00	X nn
15 Bonnet insulator clips <i>necessary</i>	10	6.50	Return	65.00	?
16 Bonnet hinge - RH / LH	2	135.00	Return	270.00	X nn
17 Bonnet spring - LH	1	28.00	Return	28.00	1 nn
18 Bonnet lock - LH	1	62.00	Return	62.00	? nn
19 Bonnet lock switch - LH	1	45.00	Return	45.00	? nn
20 Support panel	1	650.00	Return	650.00	✓
21 Support panel top garnish clips	6	5.00	Return	30.00	✓
22 Headlamp assy - RH / LH	2	1,980.00	Return	3,960.00	✓
23 Headlamp bracket - LH ✓	1	65.00	Return	65.00	?
24 Front grille	1	165.00	Return	165.00	✓
25 Front grille outer chrome	1	190.00	Return	190.00	✓
26 Front grille beam	1	225.00	Return	225.00	✓
27 Front grille beam moulding	2	58.00	Return	116.00	✓
28 Front grille support	1	178.00	Return	178.00	✓
29 Front grille inner garnish ✓	1	95.00	Return	95.00	?
30 Front bumper	1	850.00	Return	850.00	✓
31 Front bumper reinforcement	1	395.00	Return	395.00	✓
32 Front bumper bracket - LH	1	168.00	Return	168.00	? nn
33 Front bumper inner carrier - LH ✓	1	75.00	Return	75.00	?



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/08/2021

ESTIMATE

NO : QUOT202108-000029(00)

DATE : 18/08/2021

POLICY NO : 999995580

VEH REG NO : SLZ1651K

MAKE/MODEL : MERCEDES BENZ E250 AVG
(R18 LED)

CHASSIS NO : WDD2130452A414492

ENGINE NO : 27492031389300

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SLZ1651K

Description	Quantity	Unit Price	Amount
		S\$	S\$
34 Front bumper strut - LH ✓	1	42.00	42.00 ✓
35 Front bumper sponge	1	152.00	152.00 ✓
36 Front bumper centre grille	1	96.00	96.00 ✓
37 Front bumper lower inner frame ✓	1	105.00	105.00 ✓
38 Front bumper side retainer - LH	1	24.00	24.00 ✓
39 Front bumper sensor	1	138.00	138.00 ✓
40 Front bumper sensor seal	6	8.00	48.00 ✓
41 Front bumper sensor cable	1	130.00	130.00 ✓ nn
42 Front bumper clips	15	5.50	82.50 ✓
43 Front bumper lower chrome	1	118.00	118.00 ✓
44 Front bumper lower lid	1	115.00	115.00 ✓
45 Front bumper under cover - Centre.	1	168.00	168.00 ✓
46 Front number plate garnish	1	98.00	98.00 ✓ nn
47 Front fender - LH	1	628.00	628.00 ✓ XR
48 Front fender inner-shield clips - LH	20	6.50	130.00 ✓ nn
49 Front sport rim - LH photo ✓	1	750.00	750.00 ✓
			25,923.50
		Add 10%	2,464.75
			28,388.25
SPECIAL NET			
50 ERP bracket	1	35.00	35.00 ✓ 265m
51 Front windscreen sealant	1	60.00	60.00 ✓ 405m
52 Front number plate	1	40.00	40.00 ✓
			135.00
LABOUR			
53 To remove and refit air-con condenser and refill air-con gas	1	150.00	150.00 ✓ 100l
54 To remove and refit dashboard, meter and grove box compartment to facilitates the repair	1	580.00	580.00 ✓ 300l
55 To remove and refit front windscreen glass	1	150.00	150.00 ✓ 120l
56 To dismantle and refit console box to enable replace airbag control unit	1	280.00	280.00 ✓ 180l
57 To remove and replace roofing lining	1	120.00	120.00 ✓ 80l
58 To remove and replace steering aigbag, passenger airbag, knee airbag, front and rear safety belt, airbag control unit and airbag sensor	1	800.00	800.00 ✓ 400l
59 To check and rectify wiring system	1	80.00	80.00 ✓ 20l



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 3

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/08/2021

ESTIMATE

NO : QUOT202108-000029(00)

DATE : 18/08/2021

POLICY NO : 999995580

VEH REG NO : SLZ1651K

MAKE/MODEL : MERCEDES BENZ E250 AVG
(R18 LED)

CHASSIS NO : WDD2130452A414492

ENGINE NO : 27492031389300

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SLZ1651K

Description	Quantity	Unit Price	Amount
		S\$	S\$
60 To panel beat and straighten LH front fender inner panel, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,500.00	1,500.00 <i>600</i>
61 To putty and spray paint on affected areas	1	1,200.00	1,200.00 <i>600</i>
62 To re-program and reset all control module faulty code	1	580.00	580.00 <i>?</i>
			5,440.00
		TOTAL	S\$ 33,963.25
		ADD GST @ 7%	2,377.43
		GRAND TOTAL	S\$ 36,340.68

SINGAPORE DOLLAR THIRTY-SIX THOUSAND THREE HUNDRED FORTY AND CENTS SIXTY-EIGHT ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/08/2021

ESTIMATE

NO : QUOT202108-000029(00)

DATE : 24/09/2021

POLICY NO : 999995580

VEH REG NO : SLZ1651K

MAKE/MODEL : MERCEDES BENZ E250 AVG
(R18 LED)

CHASSIS NO : WDD2130452A414492

ENGINE NO : 27492031389300

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SLZ1651K

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Knee airbag under cover	1 <i>am</i>	250.90	250.90
2 Front bumper under cover - LH	1 <i>am</i>	88.00	88.00
3 Front bumper pressure sensor	1 <i>ds</i>	155.00	155.00
4 Horn bracket - RH / LH	2 <i>bt</i>	28.00	56.00
			549.90
		Add 10%	54.99
			604.89
		TOTAL	S\$ 604.89
		ADD GST @ 7%	42.34
		GRAND TOTAL	S\$ 647.23

SINGAPORE DOLLAR SIX HUNDRED FORTY-SEVEN AND CENTS TWENTY-THREE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE