

MY CAR CONSULTANT PTE LTD  
 (Co Reg. No. 201605878Z)  
 60 JALAN LAM HUAT, CARROS CENTRE  
 #05-68 (S737869)

|   |                     |            |             |
|---|---------------------|------------|-------------|
| TO  | : AIG               | DATE       | : 18-Aug-21 |
| ATTENTION                                       | : MOTOR CLAIMS DEPT | JOB TYPE   | : T/P CLAIM |
| <u>VEHICLE DETAILS</u>                          |                     |            |             |
|   |                     | VEHICLE NO | SLG3253M    |
|   |                     | MODEL      | TOYOTA WISH |
| THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482 |                     |            |             |

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

| S/N | DESCRIPTION  | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |     |
|-----|--|-----|-----------------|------------------|-----|
| 1   | FRONT BUMPER <i>X su</i>                           | 1   | \$ 698.00       | \$ 698.00        | X   |
| 2   | FRONT BUMPER SIDE RETAINER RH <i>X su</i>          | 1   | \$ 68.00        | \$ 68.00         | X   |
| 3   | HEADLAMP RH <i>X su</i>                            | 1   | \$ 859.60       | \$ 859.60        | X   |
| 4   | FRONT FENDER RH <i>bt</i>                          | 1   | \$ 898.60       | \$ 898.60        | 689 |
| 5   | FRONT FENDER COWLING RH <i>de</i>                  | 1   | \$ 196.60       | \$ 196.60        | 150 |
| 6   | FRONT QUARTER GLASS WITH MOULDING RH <i>X su</i>   | 1   | \$ 656.00       | \$ 656.00        | X   |
| 7   | FRONT DOOR VIEW MIRROR RH <i>X su</i>              | 1   | \$ 989.60       | \$ 989.60        | X   |
| 8   | FRONT DOOR RH <i>for</i>                           | 1   | \$ 1,277.90     | \$ 1,277.90      | ✓   |
| 9   | FRONT DOOR STEP GARNISH RH <i>X su</i>             | 1   | \$ 155.00       | \$ 155.00        | X   |
| 10  | FRONT DOOR STEP GARNISH INNER RH <i>X su</i>       | 1   | \$ 245.00       | \$ 245.00        | X   |
| 11  | FRONT DOOR INNER LOCK RH <i>bt</i>                 | 1   | \$ 589.00       | \$ 589.00        | 420 |
| 12  | FRONT DOOR WEATHERSTRIP RH <i>m</i>                | 1   | \$ 215.00       | \$ 215.00        | 155 |
| 13  | FRONT DOOR POWER WINDOW MOTOR RH <i>? can</i>      | 1   | \$ 589.00       | \$ 589.00        | X   |
| 14  | FRONT DOOR REGULATOR RH <i>? bt</i>                | 1   | \$ 458.00       | \$ 458.00        | 159 |
| 15  | FRONT DOOR INNER TRIM BOARD RH <i>? can</i>        | 1   | \$ 598.00       | \$ 598.00        | ✓   |
| 16  | FRONT DOOR OUTER MOULDING RH <i>X su</i>           | 1   | \$ 142.60       | \$ 142.60        | X   |
| 17  | FRONT DOOR OUTER HANDLE RH <i>X su</i>             | 1   | \$ 212.00       | \$ 212.00        | X   |
| 18  | FRONT DOOR PILLER RH <i>repair</i>                 | 1   | \$ 865.00       | \$ 865.00        | X R |
| 19  | FRONT DOOR HINGE RH <i>? Lower if X su</i>         | 1   | \$ 125.00       | \$ 250.00        | X   |
| 20  | FRONT DOOR CHROME MOULDING PROTECTOR RH <i>can</i> | 1   | \$ 259.00       | \$ 259.00        | ✓   |
| 21  | ROCKER PANEL RH <i>repair</i>                      | 1   | \$ 789.20       | \$ 789.20        | X R |
| 22  | CENTRT PILLER RH <i>repair</i>                     | 1   | \$ 854.00       | \$ 854.00        | X R |
| 23  | ABS SENSOR RH <i>X su</i>                          | 1   | \$ 357.60       | \$ 357.60        | X   |
| 24  | FRONT KNUCLE ARM RH <i>X su</i>                    | 1   | \$ 489.70       | \$ 489.70        | X   |
| 25  | FRONT KNUCLE BEARING RH <i>X su</i>                | 1   | \$ 235.90       | \$ 235.90        | X   |

Transportation:

Final Report

Date/Time, File Return to?

|    |  |        |   |             |             |    |
|----|--|--------|---|-------------|-------------|----|
| 26 | FRONT WHEEL HUP RH                     | X SUC  | 1 | \$ 494.20   | \$ 494.20   | X  |
| 27 | FRONT SHOCK ABSORBER RH                | X SUC  | 1 | \$ 488.90   | \$ 488.90   | X  |
| 28 | FRONT LOWER ARM RH                     | X SUC  | 1 | \$ 561.60   | \$ 561.60   | X  |
| 29 | REAR DOOR RH                           | repair | 1 | \$ 1,277.90 | \$ 1,277.90 | XR |
| 30 | REAR DOOR INNER TRIM BOARD RH          | X SUC  | 1 | \$ 412.00   | \$ 412.00   | X  |
| 31 | REAR DOOR BLACK STICKER RH             | X SUC  | 1 | \$ 129.00   | \$ 129.00   | X  |
| 32 | REAR DOOR CHROME MOULDING PROTECTOR RH | X SUC  | 1 | \$ 259.00   | \$ 259.00   | X  |

TOTAL PRICE \$ 16,570.90  
 LESS 25% \$ 4,142.73  
 SUB TOTAL PRICE \$ 12,428.18

3966.90  
 25%  
 2975.17

SPECIAL NETT ITEMS

| S/N | DESCRIPTION                       | QTY | UNIT S/NETT | TOTAL S/NETT |            |
|-----|-----------------------------------|-----|-------------|--------------|------------|
| 1   | FRONT BUMPER CLIP (SET)           | 1   | \$ 60.00    | \$ 60.00     | X          |
| 2   | FRONT FENDER COWLING CLIP (SET)   | 1   | \$ 50.00    | \$ 50.00     | 30         |
| 3   | FRONT QUARTER GLASS INNER SEAL RH | 1   | \$ 60.00    | \$ 60.00     | X          |
| 4   | FRONT QUARTER GLASS SEALANT       | 1   | \$ 60.00    | \$ 60.00     | X          |
| 5   | FRONT DOOR TRIM BOARD CLIP (SET)  | 1   | \$ 60.00    | \$ 60.00     | 20         |
| 6   | FRONT DOOR SEALANT RH             | 1   | \$ 80.00    | \$ 80.00     | X          |
| 7   | FRONT DOOR INNER TRIM CLIPS (SET) | 1   | \$ 32.00    | \$ 32.00     | X          |
| 8   | FRONT WHEEL TYRE RH               | 1   | \$ 320.00   | \$ 320.00    | X          |
| 9   | FRONT WHEEL RIM RH                | 1   | \$ 650.00   | \$ 650.00    | X          |
| 10  | CENTER PILLER SEALANT             | 1   | \$ 80.00    | \$ 80.00     | X          |
| 11  | CENTER PILLER INNER TRIM CLIP SET | 1   | \$ 50.00    | \$ 50.00     | X          |
| 12  | SIDE SKIRT RH                     | 1   | \$ 1,200.00 | \$ 1,200.00  | price? 680 |
| 13  | REAR DOOR INNER TRIM CLIPS (SET)  | 1   | \$ 60.00    | \$ 60.00     | X          |

TOTAL \$ 2,762.00

730

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

| S/N | JOB DESCRIPTION   | PRICE       | ADJUSTED COST |   |
|-----|---|-------------|---------------|---|
| 1   | TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK                                   | \$ 1,400.00 | 700           |   |
| 2   | TO SPRAY PAINT  | \$ 1,400.00 | 800           |   |
| 3   | TUFF COAT   | \$ 200.00   | 30            |   |
| 4   | WIRING, BULB CHECKING   | \$ 180.00   | X NN          | X |
| 5   | REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR | \$ 400.00   | X NN          | X |
| 6   | REMOVE & REFIX REAR UNDERCARRIAGE   | \$ 550.00   | X NN          | X |
| 7   | TRANFER FRONT DOOR MECHANISM  | \$ 120.00   | 60            |   |

1590

Veh No: SKC 1516J  
 Yr Regn: 2011 / MM  
 Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Date:  
 Estimated Cost:

Site Insp  
 Add Fee:  
 Photos

|    |                                      |           |      |   |
|----|--------------------------------------|-----------|------|---|
| 8  | TRANSFER REAR DOOR MECHANISM         | \$ 120.00 | X 11 | X |
| 9  | REMOVE AND REFIX FRONT UNDERCARRIAGE | \$ 500.00 | X 11 | X |
| 10 | REMOVE AND REFIT REAR QUARTER GLASS  | \$ 120.00 | X 11 | X |
| 11 | FOUR WHEEL ALIGNMENT                 | \$ 120.00 | X 11 | X |

**TOTAL \$ 5,110.00**

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 15,190.18  
 TOTAL LABOUR COST : \$ 5,110.00  
 TOTAL REPAIR COST : \$ 20,300.18

**APPROVED DETAILS**

EXCESS :  
 NO. OF WORKING DAYS : 7 days  
 RE-SURVEY :  
 PART BY PART OR **LUMP SUM** :  
 DATE & TIME OF SURVEY : 19/08/21 @ 1120  
 SURVEYED BY : RASUL  
 CONTACT NUMBER : 90010068  
 FAX NUMBER :

email : rasul@lkkauto.com

2975.17  
 730.00  
 1590.00  
 -----  
 5295.17  
 20%  
 4236.13  
 -----  
 43-\$4,200  
 -----  
 7 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: