



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
VISION LAW LLC*		Ref:	CS/LAW21008686/Duf3e2
133 NEW BRIDGE ROAD #18-01/02 CHINATOWN POINT SINGAPORE 059413		Date:	05/10/2021
		Code:	L029
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SJE 4623G	Veh. Inspected	SJU 3505L
Policy No.		Coverage (\$)	0.00
Claim No.	T140.111787.19	Excess (\$)	0.00
Assign From	TEO YI XUAN	Assign Date	18/08/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH	c.c	1987
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JTDGJ20W405001456	Colour	SILVER
Odometer	132679 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/50 R17	FIRENZA	5 mm
L/H Front Tyre	215/50 R17	FIRENZA	5 mm
R/H Rear Tyre	215/50 R17	FIRENZA	5 mm
L/H Rear Tyre	215/50 R17	FIRENZA	5 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	08/10/2019	Inspection Date	17/09/2021
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	