

not Arthur
 19/8/21
 P/P \$ 4486.10 4 days.

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3031/08/21 Your Ref:

MR TAN CHEE TONG
 BLK 231, #02-1240
 ANG MO KIO AVE 3
 SINGAPORE 560231

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

is subject to final approval from Insurance Company

Date: 18th AUG 2021
 Acknowledged by Repairer
 Signature:
 Date:

Estimate cost of repair to KIA CERATO 1.6 (A) EX Saloon - SMM 8855 A

1 pc boot lid	DD	1297		\$ 4,297.00	
1 pc boot lid logo emblems	neu			52.00	✓
1 pc boot lid n/s reflector	11			608.00	X
8 pcs boot lid insulator clips	11		3.80	30.40	X
1 pc rear bumper	De			688.00	✓
10 pcs rear bumper clips	neu	38	3.80	38.00	✓
1 pc rear bumper n/s reverse lamp assy	Su			181.00	X
1 pc rear bumper reinforcement	Cru			354.00	✓
1 pc rear bumper reinforcement n/s stay bracket	11			65.00	X
2 pcs rear bumper reinforcement o/s & n/s top bracket	11		18.00	36.00	X
3 pcs rear bumper reinforcement lower bracket	11		18.00	54.00	X
1 pc rear bumper damper	11			72.00	X
2 pcs rear bumper o/s & n/s side retainer	11		28.00	56.00	X
1 pc rear end panel	R			342.00	X
				<u>\$ 3,873.40</u>	
				Less 10%	\$ 387.34
				<u>\$ 3,486.06</u>	
1 pc rear number plate & frame	11			40.00	S.N X
1 pc boot lid spoiler sealant	11			50.00	S.N X
1 pc rear bumper lower spoiler (Sport)	car/oe			800.00	S.N X
1 set rear bumper reverse sensor	Su			200.00	S.N X
1 pc rear bumper n/s reverse lamp garnish	Su			145.00	S.N X
				<u>\$ 1,235.00</u>	S.N
To wiring check up				50.00	20
To remove & refix carpet, floor board cover, garnish, spare tyre tool set & necessary parts.				150.00	fo
To remove, refix & pump sealant for boot lid top spoiler.				150.00	50
To respray Tuff-Kote on all affected accident parts.				80.00	30
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear end panel & necessary parts, to weld, renew & align above parts.				1,000.00	520
To putty & respray painting (Pearl Colour) on all affected accident parts.				1,350.00	800
				<u>\$ 7,501.06</u>	
Dollars : Seven Thousand Five Hundred One Dollar And Cents Six Only.					

HUP MOTOR TRADING & SERVICE

P-2429
 102
 2186.1
 4486.1