

Date: 18.08.2021

Vehicle No: SMH6724J

Model: HONDA VEZEL HYBRID 1.5X

Chassis: RU31226864-2016

Reg.Year: 2019

Third Party Insurer: AIG

Third Party Veh No: SLP7782D

Date of Accident: 18.08.2021

Estimator: TING AN

Surveyor:

## ESTIMATE

| NO.         | DESCRIPTION                      | QTY | UNIT S\$ | AMOUNT S\$  |
|-------------|----------------------------------|-----|----------|-------------|
| 1           | REAR TAILGATE                    | 1   |          | Rs \$972.40 |
| 2           | REAR TAILGATE "HYBRID" EMBLEM    | 1   |          | Rs \$75.60  |
| 3           | REAR TAILGATE "VEZEL" EMBLEM     | 1   |          | Rs \$65.60  |
| 4           | REAR TAILGATE INNER LOCK         | 1   |          | \$116.40    |
| 5           | REAR TAILGATE INNER TRIM BOARD   | 1   |          | Rs \$203.50 |
| 6           | REAR TAILGATE WEATHERSTRIPE      | 1   |          | Rs \$138.60 |
| 7           | REAR WINDSCREEN MOULDING         | 1   |          | Rs \$105.20 |
| 8           | REAR TAIL LAMP LH                | 1   |          | Rs \$486.70 |
| 9           | REAR TAIL LAMP RH                | 1   |          | Rs \$486.70 |
| 10          | REAR BUMPER                      | 1   |          | Rs \$829.60 |
| 11          | REAR BUMPER SIDE BRACKET LH      | 1   |          | Rs \$37.50  |
| 12          | REAR BUMPER SIDE BRACKET RH      | 1   |          | Rs \$37.50  |
| 13          | REAR BUMPER REFLECTOR LH         | 1   |          | Rs \$108.50 |
| 14          | REAR BUMPER REFLECTOR RH         | 1   |          | Rs \$108.50 |
| 15          | REAR BUMPER SMART BUZZER         | 1   |          | \$110.10    |
| 16          | REAR SIDE BUMPER LH              | 1   |          | Rs \$148.50 |
| 17          | REAR SIDE BUMPER RH              | 1   |          | Rs \$148.50 |
| 18          | REAR END PANEL                   | 1   |          | \$452.40    |
| 19          | REAR SPARE TYRE TRAY             | 1   |          | Rs \$236.10 |
| 20          | REAR SPARE TYRE TRAY UPPER BOARD | 1   |          | Rs \$459.90 |
| SUB TOTAL   |                                  |     |          | \$5,327.80  |
| LESS 20%    |                                  |     |          | -\$1,065.56 |
| PARTS TOTAL |                                  |     |          | \$4,262.24  |

| NO.       | SPECIAL NETT                        | QTY | UNIT S\$ | AMOUNT S\$  |
|-----------|-------------------------------------|-----|----------|-------------|
| 1         | REAR TAILGATE INNER TRIM CLIPS      | 1   |          | Rs \$40.00  |
| 2         | REAR WINDSCREEN SEALANT             | 1   |          | Rs \$80.00  |
| 3         | REAR BUMPER CLIPS                   | 1   |          | Rs \$50.00  |
| 4         | REAR BUMPER REVERSE SENSOR          | 1   |          | \$300.00    |
| 5         | REAR END PANEL JOINT SEALANT        | 1   |          | \$80.00     |
| 6         | REAR END PANEL UPPER COVER (CHROME) | 1   |          | Rs \$180.00 |
| 7         | REAR BUMPER CHROME MOULDING         | 1   |          | Rs \$220.00 |
| S/N TOTAL |                                     |     |          | \$950.00    |

### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

8A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9910 | Fax: (+65) 6481 1993

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18.08.2021  
Vehicle No: SMH6724J  
Model: HONDA VEZEL HYBRID 1.5X  
Chassis: RU31226864-2016  
Reg.Year: 2019

Third Party Insurer: AIG  
Third Party Veh No: SLP7782D  
Date of Accident: 18.08.2021  
Estimator: TING AN  
Surveyor:

**LABOUR CHARGES:**

|                                                                                                                                                                     |                   |     |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-----|
| LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.                                                                                      | \$1,000.00        | ?   |
| LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR SIDE BUMPER LH, REAR SIDE BUMPER RH, REAR END PANEL & ETC. | \$1,000.00        | 600 |
| LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE.                | \$150.00          | 120 |
| LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.                                                            | \$120.00          | 60  |
| LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.                                                                                                | \$100.00          | 50  |
| TO TUFF KOTE & UNDERSEAL MATERIALS.                                                                                                                                 | \$100.00          | ?   |
| TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.                                                                                                                          | \$80.00           | 15  |
| <b>LABOUR TOTAL</b>                                                                                                                                                 | <b>\$2,550.00</b> |     |

|         |              |                   |
|---------|--------------|-------------------|
| TING AN | <b>TOTAL</b> | <b>\$7,762.24</b> |
|---------|--------------|-------------------|

**Head office**

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

