

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMR21008898/44f3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

BUS/08/21/5024


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Preli. Report

1) 29/11 TYPIST



: Final Report

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format : TP

Lump Sum / I.B.I.: (\$ 2174.70

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) _ \$ + RS _ \$

) Photos

) Others

TOTAL

(RED \$4976.30; 70%)

Insured vehicle is SMB 315C, wksp will do addendum for GIA

29/11/14 confirmed P/P \$ 2174.70 with Ben 3 repair days



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS SERVICES

SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE		NAME : ADDRESS : TEL :		WIP : 61179 EXCESS : DATE : 19-Aug-21	
ATTN : MOTOR CLAIMS FAX :		P/P # 2174.70			
VEH NO :	SLL5584T	DATE IN :		CONTACT PERSON :	RONALD
CHASSIS NO :	MM6DL2SAAGW213890	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 2	DATE REG.:	28-Feb-17	POLICY NO. :	

NATURE OF WORKS

Parts Description							
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	FENDER RHR DJ/DL	1			MDBYA-70-41X	R	\$ 886.20
2	GUARD(R),STONE-FRT DJ	1			MDB1L-50-4P2	101	\$ 14.70
3	BODY(R),DOOR MIRROR DJ/DL	1			MDB2M-69-121C	17	\$ 372.80
4	GLASS & HOLDER(R),MI	1			MDA9K-69-1G1	17	\$ 49.50
5	LAMP(R),SIDE TURN DL	1			MD09W-69-122	17	\$ 56.60
6	HOUSING(R),DR MIRROR	1			MDA6T-69-1N1 86	17	\$ 81.20
					TOTAL PARTS		\$ 1,461.00
					TOTAL PARTS COST		\$ 1,461.00

SUPPLEMENTARY

NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1							
2							
3							
					TOTAL PARTS		\$ -
					TOTAL PARTS COST		\$ -

Labour Description

		REVISED	PRICES
1	TO REPLACE REAR FENDER RH. TO REPAIR REAR DOOR RH. 660	660	\$ 2,640.00
2	TO RESPRAY REAR FENDER RH AND REAR DOOR RH. 630	1360	\$ 1,890.00
3	MZ-BR-SEALER TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	11 X	\$ 180.00

4	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	11	X	\$ 330.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120		\$ 200.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	11 X		\$ 250.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CAOUTCHOU)	11 X		\$ 150.00
8	MZ-BR-SUNDRI	SUNDRIES.	111 20		\$ 50.00

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TOTAL LABOUR	\$ -	\$ 5,690.00
TOTAL PARTS	\$ -	\$ 1,461.00
TOTAL	\$ -	\$ 7,151.00
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ 7,151.00
GST 7%	\$ -	\$ 500.57
GRAND TOTAL	\$ -	\$ 7,651.57

SUPPLEMENTARY LABOUR DESCRIPTION

		REVISED	PRICES
1	#N/A		
2	#N/A		

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TOTAL LABOUR	\$ -	\$ -
TOTAL PARTS	\$ -	\$ -
TOTAL	\$ -	\$ -
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorised Signature



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION

EUROKARS SERVICES

SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE		NAME : ADDRESS : TEL :		WIP : 61179 EXCESS : DATE : 19-Aug-21	
ATTN. : MOTOR CLAIMS FAX :					
VEH NO :	SLL5584T	DATE IN :		CONTACT PERSON :	RONALD
CHASSIS NO :	MM6DL25AAGW213890	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 2	DATE REG.:	28-Feb-17	POLICY NO. :	

<u>NATURE OF WORKS</u>						
<u>Parts Description</u>						
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED PRICES
1	FENDER RHR DJ/DL	1			MDBYA-70-41X	\$ 886.20
2	GUARD(R),STONE-FRT DJ	1			MD81L-50-4P2	\$ 14.70
3	BODY(R),DOOR MIRROR DJ/DL	1			MD82M-69-121C	\$ 372.80
4	GLASS & HOLDER(R),MI	1			MDA9K-69-1G1	\$ 49.50
5	LAMP(R),SIDE TURN DL	1			MD09W-69-122	\$ 56.60
6	HOUSING(R),DR MIRROR	1			MDA6T-69-1N1 86	\$ 81.20
TOTAL PARTS						\$ 1,461.00
TOTAL PARTS COST						\$ 1,461.00

<u>SUPPLEMENTARY</u>						
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED PRICES
1						
2						
3						
TOTAL PARTS						\$ -
TOTAL PARTS COST						\$ -

<u>Labour Description</u>				REVISED	PRICES
1		TO REPLACE REAR FENDER RH. TO REPAIR REAR DOOR RH		\$ 660.00	\$ 2,640.00
2		TO RESPRAY REAR FENDER RH AND REAR DOOR RH		\$ 1,360.00	\$ 1,890.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		\$ -	\$ 180.00

4	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	\$ -	\$ 330.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 200.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	\$ -	\$ 250.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CAOUTCHOU)	\$ -	\$ 150.00
8	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 50.00
<u>REMARKS:</u> 3 Repair Days			TOTAL LABOUR	\$ 2,160.00 \$ 5,690.00
			TOTAL PARTS	\$ 14.70 \$ 1,461.00
			TOTAL	\$ 2,174.70 \$ 7,151.00
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 2,174.70 \$ 7,151.00
			GST 7%	\$ 152.23 \$ 500.57
			GRAND TOTAL	\$ 2,326.93 \$ 7,651.57
SUPPLEMENTARY LABOUR DESCRIPTION				
			REVISED	PRICES
1		#N/A		
2		#N/A		
<u>REMARKS:</u>			TOTAL LABOUR	
			TOTAL PARTS	
			TOTAL	
			LESS EXCESS	
			TOTAL AFTER EXCESS	
			GST 7%	
			GRAND TOTAL	

TRANS EUROKARS PTE LTD

Authorised Signature